

ASS. REC. BY:

REF:

C72/ 220118081kg3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

GIA not ready

19/12 11:00 @ 10, 15th Carport (Red @ 17300.10, 63%)

Date/Time, File Pass to?

06/11/2022

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

14

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Veh No:

SMH 87757

Yr Regn:

02.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

C.C.

1317

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

78183

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK3

1335480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

175/70R4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

15/11/22

D.O.I.

18/11/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

10/50

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

*Not Authorized
 L1 Rep & 10,150k
 Penny After Paym
 14days*

M/s China Taiping Insurance (S) Pte Ltd	DATE	17.11.2022
3 Anson Road #16-00 Spring leaf Tower	CAR NO	SMH 8775 Z
Singapore 079909	MAKE	Honda Fit

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBK 6421 Y

Pc	Pcs	GK31335480	UNIT PRICE	AMOUNT
		Recommended Parts		
1	pc	Front bonnet		\$537.40
1	pc	Front bonnet garnish		\$100.90
2	pcs	Front bonnet hinge (LH & RH)	\$35.40	\$70.80
1	pc	Front bonnet lock		\$111.40
1	pc	Front bonnet insulator		\$89.10
1	pc	Front bonnet rubber		\$58.40
1	pc	Front radiator grille		\$254.30
1	pc	Front radiator grille (chrome) upper garnish		\$150.30
1	pc	Front radiator grille (chrome) lower garnish		\$177.40
1	pc	Front lower grille		\$50.40
1	pc	Front bumper		\$801.40
10	pcs	Front bumper clips	\$5.00	\$50.00
2	pcs	Front bumper side retainer (LH & RH)	\$19.40	\$38.80
2	pcs	Front fog lamp garnish (LH & RH)	\$35.30	\$70.60
1	pc	Front bumper under cover		\$288.40
10	pcs	Front bumper under cover clips	\$5.00	\$50.00
1	pc	Front bumper reinforcement		\$388.40
2	pcs	Front head lamp (LH & RH)	\$795.40	\$1,590.80
2	pcs	Front head lamp bracket (LH & RH)	\$35.10	\$70.20
1	pc	Front support panel		\$611.70
1	pc	Front support panel top garnish		\$77.40
5	pcs	Front support panel top garnish clips	\$5.00	\$25.00
1	pc	Air guide for air inlet		\$41.70
1	pc	Front radiator		\$1,250.40
1	pc	Air con condenser		\$1,107.40
1	pc	Air con fan motor		\$310.40
1	pc	Air con fan shroud		\$117.40
1	pc	Honda emblem		\$28.40
1	pc	Front number plate with casing		\$60.00
			Total	

Page 1 of 4

Total

Susan Lim

KENT SENG CAR SERVICES.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 17.11.2022
3 Anson Road #16-00 Spring leaf Tower CAR NO SMH 8775 Z
Singapore 079909 MAKE Honda Fit

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : GBK 6421 Y

Pc	Pcs	GK31335480	UNIT PRICE	AMOUNT
		Continue from page one.		\$8,578.80
1	pc	Rear bumper		\$529.10
2	pcs	Rear bumper side retainer (LH & RH)	\$18.70	\$37.40
10	pcs	Rear bumper clips	\$5.00	\$50.00
2	pcs	Rear bumper black garnish (LH & RH)	\$30.40	\$60.80
1	pc	Rear bumper center garnish		\$76.10
1	set	Rear bumper reverse sensor		\$401.70
1	pc	Rear bumper lower lip		\$395.00
2	pcs	Tail lamp (LH & RH)	\$310.70	\$621.40
1	pc	Tailgate		\$877.90
2	pcs	Tailgate hinge (LH & RH)	\$77.10	\$154.20
2	pcs	Tailgate absorber (LH & RH)	\$117.40	\$234.80
1	pc	Third brake lamp		\$201.70
2	pcs	Tailgate reflector lamp (LH & RH)	\$211.70	\$423.40
1	pc	Tailgate garnish		\$188.40
1	pc	Tailgate "Honda" emblem		\$30.90
1	pc	Tailgate "FIT" emblem		\$42.40
1	pc	Tailgate weather strip		\$88.40
1	pc	Tailgate lock		\$155.40
1	pc	Tailgate lock outer handle garnish		\$201.90
2	pcs	Tailgate number plate lamp	\$54.30	\$108.60
1	pc	Tailgate wiper blade		\$39.10
1	pc	Tailgate wiper motor		\$301.40
1	pc	Tailgate inner shield board		\$301.40
10	pcs	Tailgate inner shield board clips	\$5.00	\$50.00
1	pc	Tailgate wind screen		\$825.60
1	pc	Tailgate wind screen moulding		\$107.40
1	pc	Rear reverse camera		\$620.00
1	pc	Rear end panel		\$601.70
1	pc	Rear end panel top garnish		\$120.70
10	pcs	Rear end panel top garnish clips	\$5.00	\$50.00
Page 2 of 4			Total	

Susan Lim

KENT SENG CAR SERVICES.

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 17.11.2022
 3 Anson Road #16-00 Spring leaf Tower CAR NO SMH 8775 Z
 Singapore 079909 MAKE Honda Fit

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBK 6421 Y

Pc	Pcs	GK31335480	UNIT PRICE	AMOUNT
		Continue from page two.		\$16,475.60
1	pc	Rear boot tray		
2	pcs	Rear fender upper inner shield board (LH & RH)	\$260.70	\$521.40
2	pcs	Rear fender lower inner shield board (LH & RH)	\$260.70	\$521.40
2	pcs	Spare tyre panel		\$750.40
1	pc	Rear LH fender		\$608.40
1	pc	Rear RH fender mudflap		\$74.30
1	pc	Rear LH fender quarter glass moulding		\$117.40
1	pc	Rear RH door		\$844.10
1	pc	Rear exhaust pipe		\$588.40
208				
Page 3 of 4				Total

Susan Lim

KENT SENG CAR SERVICES.

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 17.11.2022
 3 Anson Road #16-00 Spring leaf Tower CAR NO SMH 8775 Z
 Singapore 079909 MAKE Honda Fit

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBK 6421 Y

Pc	Pcs	GK31335480	UNIT PRICE	AMOUNT
		Continue from page three.		\$20,790.10
		Recommended Labour		
		Straightening and panel beating on all accident affected parts, cutting rear right side fender, rear spare tyre tank panel, rear end panel, front top panel, dismantle & replace front & rear damage parts.		\$3,000.00 1300
		Labour for respray front bonnet cover, front bumper, front support panel, rear bumper, tailgate, rear end panel, rear spare tyre tank panel, rear left and right side fender.		\$2,800.00 1800
		To testing, checking, dismantle and replace rear reverse sensor.		\$100.00 60
		To spray anti-rust coating on new & affected panels.		\$150.00 90
		To apply silicon onto rear wind screen.		\$80.00 40
		Labour for dismantle & refix rear wind screen.		\$180.00 120
		To perform water leakage test.		\$150.00 20
		To transfer boot lid locking mechanism and other components to new tailgate.		\$200.00 60
Page 4 of 4			Total	\$27,450.10

Susan Lim

KENT SENG CAR SERVICES.