

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 16-Nov-22

Estimate no.

1190

Plate No. FBK9955D

Model. KTM RC200

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 1,800.00	? Dent Local Repair	
2	FORK T-UNDER BRACKET	\$ 850.00	? Dent 580	
3	STEERING CONE	\$ 280.00	? KVN 120	
4	FRONT SPORT RIM	\$ 800.00	? Scr R	
5	FRONT TYRES SHAFT	\$ 180.00	? Dent 70	
6	FRONT BALANCER	\$ 120.00	cut /	
7	FRONT FENDER	\$ 150.00	Br 130	
8	FRONT DISC BRAKE	\$ 220.00	? xvn	
9	FRONT CALIPER	\$ 350.00	? Scr 260	
10	FRONT TYRES SHAFT	\$ 120.00	? Reapent	
11	HANDLE BAR RIGHT	\$ 400.00	Br } 280	
12	HANDLE BAR LEFT	\$ 400.00	Br }	
13	HANDLE BRACKET	\$ 320.00	Dent 100	
14	MASTER PUMP	\$ 280.00	Br 130	
15	BRAKE LEVER	\$ 100.00	cut 67	
16	MIRROR RIGHT	\$ 200.00	missing } 80	
17	MIRROR LEFT	\$ 200.00	missing }	
18	HANDLE GRIP	\$ 80.00	cut 25	
19	HANDLE BAR END	\$ 100.00	Br 60	
20	STARTER SWITCH	\$ 280.00	Br /	
21	HORN SWITCH	\$ 250.00	Br 170	
22	IU UNIT	\$ 155.80	Br /	
23	IU BRACKET	\$ 50.00	Dent /	
24	HEAD LAMP	\$ *900.00	Br 280	
25	HEAD LAMP STAY	\$ 400.00	Br /	
26	DAY LIGHT	\$ *650.00	Cr 280	
27	HEAD COVER	\$ 200.00	Br /	
28	WINDSHIELD	\$ 450.00	Cr 150	
29	METER	\$ 1,200.00	? Cr 523	

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzattlemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 16-Nov-22

Estimate no.

1190

Plate No. FBK9955D

Model. KTM RC200

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
30	FRONT SIGNAL LIGHT RIGHT	\$ 120.00	lvx /	
31	FRONT SIGNAL LEFT	\$ 120.00	cut /	
32	CLUTH LEVER	\$ 100.00	cut 61	
33	BRAKE HOSE	\$ 150.00	sur	
34	FRONT FAIRING COVER RIGHT	\$ *300.00	cut 120	
35	FRONT FAIRING INNER COVER RIGHT	\$ *220.00	cut 100	
36	FUEL TANK COVER	\$ 250.00	? sur /	
37	BODY UNDER COVER	\$ *200.00	? cut 120	
38	BRAKE PEDAL	\$ 200.00	BT 90	
39	FRONT FOOTREST RIGHT	\$ 150.00	sur 70	
40	FRONT FOOTREST BRACKET RIGHT	\$ 280.00	sur 85	
41	EXHAUST PIPE	\$ *1,500.00	sur ? R	
42	EXHAUST COVER	\$ 180.00	sur x NVN	
43	REAR FOOTREST RIGHT	\$ 120.00	cut 50	
44	REAR FOOTREST BRACKET RIGHT	\$ 250.00	? sur x sur	
45	REAR SPORT RIM	\$ 700.00	? x NVN	
46	BODY ALIGNMENT	\$ 500.00	? no ont (Locat) repair	
47	TROTTLE CABLE	\$ 180.00	wx 30	
48	CLUTH CABLE	\$ 150.00	wx 50	
49	FRONT FAIRING COVER LEFT	\$ *300.00	? sur 100	
50	FRONT FAIRING INNER COVER LEFT	\$ *220.00	? sur 80	
51	FRONT NUMBER PLATE	\$ 30.00	new /	
52	PANEL COVER	\$ *180.00	? BT 80	
53	SPRAY COVERSET	\$ 500.00	x NVN	
54	REAR FAIRING COVER RIGHT	\$ 250.00	? sur	
55	LABOUR	\$ 700.00	500	

TP = 6466.80
 10% = 646.68
 = 5820.12
 T = 6320.12
 20% = 1264.02
 = 5056 ≈ 5050
 5 day L/S
 After paid
 24/11/22
 5:18pm

- LKK Auto Consultants** hence notify the Repairer of the following:

 - To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10% \$ 1,933.58
 \$ 19,335.80
 Sub Total : \$ 17,402.22
 GST 7% \$ 1,218.16
 Total: \$ 18,620.38

Acknowledged by Repairer
 Signature:

* Estimate given are base on visible damages ONLY before dismantling of the vehicle*

This is computer generated no signature is required.