

Auto Insure Pte Ltd (HQ) (Co.Reg.No.201437380M)

6 Marsiling Lane
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
NAM SOON DELIGHTS PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/11/2022
Vehicle Reg. No.:	GBJ8014G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA HIACE, 2.0 (M)	Vehicle Reg. Date:	19/08/2019
Vehicle Colour:	METALLIC SILVER	Gen Condition:	FAIR
Engine No:	1GD8356570	Chassis No:	GDH2012004010
Odometer:	0 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	1,578.50
Miscellaneous Items	85.00
Labour	1,000.00
Paintwork Labour	400.00
Towing	0.00
Gross Total (S\$)	3,063.50
+ GST 7.00% (S\$)	214.45
Nett Amount (S\$)	3,277.95

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Nov 2022)
 Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Auto Insure Pte Ltd (HQ)/GBJ8014G/22/11/2022 15:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>ll</i>	0.00	0.00	*205.00 F
2	1		*FRONT BUMPER SIDE RETAINER RH <i>hl</i>	0.00	0.00	*40.00 F
3	1		*FRONT HEADLAMP RH <i>af</i>	0.00	0.00	*360.00 F
4	1		*FRONT DOOR RH <i>hl</i>	0.00	0.00	*650.00 F
5	1		*FRONT FENDER RH <i>mc</i>	0.00	0.00	*80.00 F
6	1		*FRONT DOOR UPPER HINGE RH <i>X</i>	0.00	0.00	*50.00 F
7	1		*FRONT DOOR LOWER HINGE RH <i>X</i>	0.00	0.00	*50.00 F

F=Franchise part.

Sub Total (S\$) 1,435.00
 + Margin on L,N Items 10.00% (S\$) 143.50
 Total Parts (S\$) 1,578.50

Auto Insure Pte Ltd (HQ)/GBJ8014G/22/11/2022 15:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	FRONT BUMPER CLIPS	50.00
2	FRONT DOOR COMPANY STICKER RH	35.00
Sub Total (S\$)		85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	300 400.00
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	300 800.00
3	LABOUR TO REMOVE AND REFIT FRONT DOOR MECHANISMS RH	New	60 200.00
Gross Labour Cost (S\$)			1,400.00

Auto Insure Pte Ltd (HQ)/GBJ8014G/22/11/2022 15:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 Days.

4/5

After repair photos

Gino Ang

24/11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices a copy of their confirmation
- Third party insurance on "without prejudice" basis
- No illegal work to be carried out
- Suppliers to be approved and surveyed and is subject to approval from Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____