



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE			Ref: CC4/ASM22011813/Apa3q2 Date: 14/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 5456T	Veh. Inspected	SMJ 8319Y	
Policy No.	GA324903	Coverage (\$)	0.00	
Claim No.	S2M04FEN	Excess (\$)	0.00	
Assign From		Assign Date	24/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JF1SJ5KC5JG112809	Colour	SILVER	
Odometer	69918 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	FALKEN	6 mm	
L/H Front Tyre	225/60 R17	FALKEN	6 mm	
R/H Rear Tyre	225/60 R17	FALKEN	6 mm	
L/H Rear Tyre	225/60 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2022	Inspection Date	24/11/2022	
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	