

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011814/SNP3E2**Date:** 16/12/2022**REFERENCE****Insured/Claimant:** YAP KIAN HENG **Policy No:** DMPCSNW00182002100**Date of Loss:** 22/11/2022 **Nature of Claim:** OD **Claim No:** SNM22D208423/C01/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SKV3862M**Make & Model:** HONDA CIVIC, 1.6 L VTI (A)**Engine No:** R16A13002426**Reg. Date:** 14/02/2008 (Man. Year: 2007)**Chassis No:** JHMF46208S200820**Colour:** White**Odometer:** 166090 km**Engine Capacity:** 1595 cc**Market Value/New Car Price:** S\$2,800.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 205/55 R16**Rear Tyre Size:** 205/55 R16**Front Left Side:** KAPSEN 5 mm**Rear Left Side:** KAPSEN 5 mm**Front Right Side:** KAPSEN 5 mm**Rear Right Side:** KAPSEN 5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	3,500.00	-3,500.00	
Nett Amount (S\$)	0.00	-3,500.00	3,500.00	

INSPECTION**Date of Assignment:** 23/11/2022 **Present Location:** Jin Auto Services Pte Ltd (Defu)**Date Inspected:** 24/11/2022 **Inspected At:** Jin Auto Services Pte Ltd (Defu)Blk 14 Defu Lane 10, #01-410/412
Singapore 539195**Estimated Period of Repair:** 0.0 days**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$ 2,800.00
OMV :	\$19,463.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$21,061.00
COE Rebate (2) :	\$ 898.00
Total Rebate (1) + (2) = :	\$ 898.00

The total amount incurred will be Market Value \$2,800.00 minus Total Rebate \$898.00 = \$1,902.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2022)
Parts:	143	HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3862M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >