

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Xiao Tony ✓

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/01058/2022/EQ 9-Jan-23 CHANG 1 of 1 SMY 9073 U AUDI Q3 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	RETAINER FOR AERIAL - LH	\$ 28.00	✓ ✓ ✓
2	TELEPHONE AERIAL - LH	\$ 192.00	
3	REAR LID BUNGS	\$ 133.00	
GRAND TOTAL		\$ 353.00	

For Premium Automobiles Pte Ltd


 Authorised Signature

Adrian Ling
Resurged
HL



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9073 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR SPARE WHEEL HOUSING. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 5,000.00	1250 (End Panel Repair) 2500 (End Panel) Replaced
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING. ✓ ✓	\$ 4,000.00	2200
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,712.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9073 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓ <i>[Signature]</i>
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	✓
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	✓
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,520.00	

Car in 22/12/22

w/p= 52134

PREMIUM AUTOMOBILES

Bendi.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

119-Adnan → MS.
- 5/8 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER } Distorted	1	\$ 1,958.00 ✓	
2	REAR BUMPER SPOILER }	1	\$ 510.00 ✓	
3	REAR BUMPER TOW EYE COVER n/w	1	\$ 48.00 ✗	
4	REAR BUMPER BRACKET ?	1	\$ 53.00	
5	REAR BUMPER REFLECTOR - LH / RH kit com Lnd	2	\$ 92.00 46.	
6	REAR LICENCE PLATE LIGHT - LH / RH n/w	2	\$ 113.00 ✗	
7	REAR INNER TAIL LIGHT - LH / RH n/w	2	\$ 2,060.00 ✗	
8	REAR INNER TAIL LIGHT TRIM - LH / RH n/w	2	\$ 68.00 ✗	
9	REAR BOOT LID OPENING CONTROL UNIT n/w	1	\$ 484.00 ✗	
10	REAR TAILGATE OPENING SENSOR LINE n/w	1	\$ 228.00 ✗	
11	REAR AERIAL KEY ACCESS ?	1	\$ 79.00 ?	
12	REAR PARKING AID SENSOR - INNER / OUTER 1 piece missing	3	\$ 797.00 265.6.	
13	REAR PARKING AID SEAL RING ?	4	\$ 10.00 ?	
14	REAR BUMPER WIRING SET n/w not cut	1	\$ 449.00 ✗	sls
15	REAR BUMPER REINFORCEMENT BEAM dented	1	\$ 693.00 ✓	
16	REAR BUMPER HOLDING STRAP - CENTER ?	1	\$ 120.00 ?	
17	REAR BUMPER GUIDE SECTION - LH / RH n/w	2	\$ 142.00 ✗	
18	REAR LID dented	1	\$ 3,767.00 ✓	
19	PACKING ADHESIVE n/w	1	\$ 21.00 ✓	
20	REAR LID HINGE - LH / RH n/w	2	\$ 331.00 ✗	
SUB TOTAL SPARE PARTS:			\$ 12,023.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR LID ATTACHMENT PARTS <i>see u</i>	1	\$ 393.00	+
2	REAR LID LOCK	1	\$ 293.00	+
3	REAR LID LOCK COVER	1	\$ 8.00	+
4	REAR LID STRIKER PLATE	1	\$ 74.00	+
5	REAR LID FLAP GASKET <i>see u</i>	1	\$ 229.00	+
6	REAR LID LOCK ACTUATOR CAMERA PUSHBUTTON <i>see u</i>	1	\$ 1,478.00	+
7	REAR LID STOP BUFFER - LH / RH <i>see u</i>	2	\$ 61.00	+
8	AUDI EMBLEM	1	\$ 144.00	✓
9	"Q3" INSCRIPTION	1	\$ 104.00	✓
10	REAR WINDOW	1	\$ 1,064.00	✓
11	WINDOW PRIMER	1	\$ 22.00	✓
12	REAR TAILGATE SPOILER - LH / RH	2	\$ 470.00	✓
13	REAR WHEEL COVER - LH / RH	2	\$ 566.00	✓
14	REAR CROSS PANEL dent <i>Dented</i>	1	\$ 329.00	✓
15	REAR CROSS PANEL REINFORCEMENT <i>Dented</i>	1	\$ 726.00	✓
16	REAR CROSS PANEL CONNECTING PLATE - LH / RH <i>2H dent</i>	2	\$ 92.00	✓ 46.
17	REAR LID TRIM PANEL - LOWER <i>see u</i>	1	\$ 541.00	+
18	REAR CROSS PANEL TRIM ?	1	\$ 213.00	?
19	REAR LUGGAGE COMPARTMENT FLOOR COVERING <i>see u</i>	1	\$ 993.00	+
20	REAR SILENCER HEAT SHIELD ?	1	\$ 129.00	?
SUB TOTAL SPARE PARTS			\$ 7,929.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR UNDERBODY TRIM - LH / RH <i>me a</i>	2	\$ 121.00	+
22	REAR WHEEL HOUSING LINER - LH / RH <i>me a</i>	2	\$ 524.00	+
23	ACRYLIC SEALANT <i>me</i>	S/N	\$ 180.00	✓
24	CAVITY WAX <i>me</i>	S/N	\$ 140.00	✓
25	STONE CHIP <i>me</i>	S/N	\$ 180.00	✓
26	METAL FILLER POWDER <i>me</i>	S/N	\$ 280.00	✓
27	REAR NO PLATE <i>del d</i>	S/N	\$ 60.00	✓
28	REAR WINDSCREEN SEALANT <i>me</i>	S/N	\$ 200.00	✓
29	SUNDRIES ?		\$ 600.00	?
TOTAL SPARE PARTS		:	\$ 22,237.00	
TOTAL LABOUR CHARGES		:	\$ 12,712.00	
GRAND TOTAL		:	\$ 34,949.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.