



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/01058/2022/EQ  
**DATE** : 25-Nov-22  
**WIP** : 52134

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/2022**

**YOUR INSURED VEH NO : SGL 7113 R**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR SIM SOON CHYE, EDMUND (SHEN SHUNCAI,EDMUND)  
**ADDRESS** : BLK 444 ANG MO KIO AVENUE 10  
#08-1597  
SINGAPORE 560444  
**TELEPHONE** : HP +65 96532982  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 7210032459  
**VEHICLE NO** : **SMY 9073 U**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S-TRONIC  
**MODEL YEAR** : 30/3/2021  
**ENGINE NO** : CZD C28969  
**CHASSIS NO** : WAUZZZF32M1076450  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 23-Nov-22  
**PLACE OF ACCIDENT** : LOWER DELTA ROAD TOWARDS JALAN BUKIT MERAH

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9073 U**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	
4	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,520.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 9073 U**

<b>S/N</b>	<b>NATURE OF JOBS</b>	<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR SPARE WHEEL HOUSING. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,000.00	
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$ 4,000.00	
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 12,712.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	REAR BUMPER	1	\$ 1,958.00	
2	REAR BUMPER SPOILER	1	\$ 510.00	
3	REAR BUMPER TOW EYE COVER	1	\$ 48.00	
4	REAR BUMPER BRACKET	1	\$ 53.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
6	REAR LICENCE PLATE LIGHT - LH / RH	2	\$ 113.00	
7	REAR INNER TAIL LIGHT - LH / RH	2	\$ 2,060.00	
8	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$ 68.00	
9	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 484.00	
10	REAR TAILGATE OPENING SENSOR LINE	1	\$ 228.00	
11	REAR AERIAL KEY ACCESS	1	\$ 79.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	3	\$ 797.00	
13	REAR PARKING AID SEAL RING	4	\$ 10.00	
14	REAR BUMPER WIRING SET	1	\$ 449.00	
15	REAR BUMPER REINFORCEMENT BEAM	1	\$ 693.00	
16	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 120.00	
17	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 142.00	
18	REAR LID	1	\$ 3,767.00	
19	PACKING ADHESIVE	1	\$ 21.00	
20	REAR LID HINGE - LH/ RH	2	\$ 331.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 12,023.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR LID ATTACHMENT PARTS	1	\$ 393.00	
2	REAR LID LOCK	1	\$ 293.00	
3	REAR LID LOCK COVER	1	\$ 8.00	
4	REAR LID STRIKER PLATE	1	\$ 74.00	
5	REAR LID FLAP GASKET	1	\$ 229.00	
6	REAR LID LOCK ACTUATOR CAMERA PUSHBUTTON	1	\$ 1,478.00	
7	REAR LID STOP BUFFER - LH / RH	2	\$ 61.00	
8	AUDI EMBLEM	1	\$ 144.00	
9	"Q3" INSCRIPTION	1	\$ 104.00	
10	REAR WINDOW	1	\$ 1,064.00	
11	WINDOW PRIMER	1	\$ 22.00	
12	REAR TAILGATE SPOILER - LH / RH	2	\$ 470.00	
13	REAR WHEEL COVER - LH /RH	2	\$ 566.00	
14	REAR CROSS PANEL	1	\$ 329.00	
15	REAR CROSS PANEL REINFORCEMENT	1	\$ 726.00	
16	REAR CROSS PANEL CONNECTING PLATE - LH / RH	2	\$ 92.00	
17	REAR LID TRIM PANEL - LOWER	1	\$ 541.00	
18	REAR CROSS PANEL TRIM	1	\$ 213.00	
19	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$ 993.00	
20	REAR SILENCER HEAT SHIELD	1	\$ 129.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 7,929.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 9073 U**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
21	REAR UNDERBODY TRIM - LH / RH	2	\$ 121.00	
22	REAR WHEEL HOUSING LINER - LH / RH	2	\$ 524.00	
23	ACRYLIC SEALANT	S/N	\$ 180.00	
24	CAVITY WAX	S/N	\$ 140.00	
25	STONE CHIP	S/N	\$ 180.00	
26	METAL FILLER POWDER	S/N	\$ 280.00	
27	REAR NO PLATE	S/N	\$ 60.00	
28	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
29	SUNDRIES		\$ 600.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 22,237.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 12,712.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 34,949.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT