

[illegible]



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC577
Vehicle No. : SML4168G
Make & Model : VOLKSWAGEN TOUAN 1.4

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	100.00 ✓	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	200.00	100
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
		230	
Labour Total :		360.00	
TOTAL (PARTS & LABOUR):		1470.60	

Tanfjin 97495749 / 62565561

WP' 24/11/22 @ 3pm

& Resurvey new parts
old day

tanfjin @ lkhauto.com.

1110.60
230
\$1340.60
01 DAY #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: