

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011825/AQP3M4
Date: 09/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00246532101	
Claimant Vehicle No :	SKP3696H	Insured Vehicle No :	SMM4021R	
Date of Loss:	18/11/2022	Nature of Claim:	TP	Claim No: SNM22D208350/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP3696H			
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	07197667N52B25AF	
Reg. Date:	25/02/2011 (Man. Year: 2010)	Chassis No:	WBAFP32060C863790	
Colour:	Black	Odometer:	220115 km	
Engine Capacity:	2497 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	10,614.00	4,876.60	5,737.40	54.06	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,350.00	1,150.00	1,200.00	51.06	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	12,964.00	6,026.60	6,937.40	53.51	
Approved Total (Overridden) (S\$)		4,800.00			
	(S\$)	12,964.00	4,800.00	8,164.00	62.97
+ GST 8.00/8.00% (S\$)		1,037.12	384.00	653.12	62.97
Nett Amount (S\$)	14,001.12	5,184.00	8,817.12	62.97	

INSPECTION

Date of Assignment:	23/11/2022		
Date Inspected:	28/11/2022	Inspected At:	ONE GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts: 143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP3696H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,480.00 F	*- FL
2	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	110.00 F	*- FL
3	1		*FRONT BUMPER SENSOR	Not Necessary	285.00 F	*- FL
4	1		*FRONT LH FENDER	Dented	988.00 F	*988.00 FL
5	1		*FRONT LH DOOR	Repair	1,985.00 F	*- FL
6	1		*HEADLAMP LH	Cracked	2,486.00 F	*2,486.00 FL
7	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
8	1		*FRONT LH FENDER GARNISH	Cut	180.00 FS	*120.00 FS
9	1		*FRONT LH FENDER GARNISH CHROME MOULDING	Necessary	50.00 FS	*30.00 FS
10	2		*FRONT WHEEL RIM	Cut	3,000.00 FS	*1,600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,614.00	5,224.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	347.40
Total Parts (\$\$)	10,614.00	4,876.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			2,350.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >