



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22011827/Tvy3 Date: 24/11/2022 Code: SMR	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
	Insured Veh.	SHB 21J	Veh. Inspected	FBT 8920M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/22/2010/AL	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	24/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	07/11/2022	Inspection Date	24/11/2022
	Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			