

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHA649D**
 MAKE **REG 15.09.2016**
 MODEL **HYU- I40**

DATE **15.11.2022**
CHIANG /CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT FENDER LH <i>scr dent</i>			\$663.00
1	FRONT FENDER SHIELD LH <i>?X NN</i>			\$174.90
1	HEAD LAMP LH <i>?X NN</i>			\$1,388.00
1	FRONT BUMPER SIDE /LH <i>scr X</i>		\$24.60	\$49.20
1	FRONT BUMPER <i>scr #</i>			\$1,052.20
1	FRONT BUMPER GRILLE LH <i>?X NN</i>			\$187.20
	SUB TOTAL		1715	\$3,514.50
	20.00%		343	\$702.90
	DISCOUNTED TOTAL		1372	\$2,811.60
	Labour Charge			
	Panel Beating			\$560.00
	Spray Painting Charge			\$600.00
	Check wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR		830	\$1,280.00
	ESTIMATE TOTAL		2200	\$4,091.60
			20% = 440	
			Final = 1760	
			~1750	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

30
50
30
X

1 rfm 90097659

16/11/22 340pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*By L15 After paint.
3 days.*