



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA			Ref: CC4/ASM22011834/Rpa3q2 Date: 21/02/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 4542B	Veh. Inspected	SMA 3800D
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04FFI	Excess (\$)	0.00
	Assign From		Assign Date	24/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLKSWAGEN GOLF 1.4 TSI	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WVWZZZAUZLW007856	Colour	GREY
	Odometer	24986 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	PIRELLI	6 mm
	L/H Front Tyre	225/40 R18	PIRELLI	6 mm
	R/H Rear Tyre	225/40 R18	PIRELLI	6 mm
	L/H Rear Tyre	225/40 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	24/11/2022	Inspection Date	25/11/2022
	Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	