

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 20/11/2022

Estimated repair cost for vehicle no: GBG9986K TOYOTA HIACE SUPER GL DARK PRIME 3.0
AUTO

CHASSIS: KDH2010236067 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR TAILGATE <i>Dented</i>	\$1,654.10	\$1,654.10 ✓
2	1	REAR TAILGATE INNER TRIM <i>New</i>	\$276.40	\$276.40 +
3	1	REAR TAILGATE LOCK <i>2nd</i>	\$254.70	\$254.70 ✓
4	1	REAR TAILGATE LOCK CATCH <i>New</i>	\$110.30	\$110.30 +
5	1	REAR TAILGATE LOGO <i>New</i>	\$59.30	\$59.30 ✓
6	1	REAR TAILGATE EMBLEM HIACE <i>3 new</i>	\$55.60	\$55.60 ✓
7	1	REAR TAILGATE EMBLEM SUPER GL	\$65.30	\$65.30 ✓
8	1	REAR BUMPER <i>Dented</i>	\$598.60	\$598.60 ✓
9	1	REAR BUMPER SIDE RETAINER RH <i>New</i>	\$67.20	\$67.20 ✓
10	1	REAR END PANEL (INNER) <i>Dented</i>	\$547.10	\$547.10 +
11	1	REAR END PANEL (OUTER) <i>Dented</i>	\$852.20	\$852.20 597
12	1	REAR END PANEL EXTENSION PANEL RH <i>Dented</i>	\$398.40	\$398.40 ✓
13	1	REAR END PANEL TOP GARNISH <i>New</i>	\$112.30	\$112.30 +
14	1	REAR WEATHER STRIPE <i>New</i>	\$326.80	\$326.80 x
15	1	REAR TAILLAMP RH <i>Cracked</i>	\$397.60	\$397.60 ✓
16	1	REAR TAILLAMP INNER PANEL <i>Right</i>	\$297.10	\$297.10 +
17	1	REAR TAILLAMP LOWER BRACKET RH <i>New</i>	\$67.40	\$67.40 +
18	1	REAR TAILGATE LOWER APRON PANEL RH <i>Dented</i>	\$387.10	\$387.10 102

TOTAL : \$6,527.50

LESS 25 % \$1,631.88

SUB-TOTAL : \$4,895.63

4249.80

3187.35

GBG9986K TOYOTA HIACE SUPER GL DARK

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>Rev</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR WINDSCREEN GLASS SEALANT <i>Rev</i>	\$150.00	\$150.00 <i>60</i>
3	1	REAR END PANEL SEALANT <i>Rev</i>	\$120.00	\$120.00 <i>60</i>
4	1	REAR REVERSE SENSOR <i>Rev</i>	\$280.00	\$280.00 <i>200</i>
5	1	REAR REVERSE CAMERA <i>Rev</i>	\$480.00	\$480.00 <i>+</i>

350

TOTAL: \$1,110.00

TOTAL PARTS : \$6,005.63

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS
- 4 WIRING CHECK
- 5 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS
- 6 LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING

1000 \$1,500.00
900 \$1,000.00
120 \$150.00
30 \$80.00
2210 *80* \$200.00
80 \$300.00

Subtotal :- \$3,230.00

Total:- \$9,235.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian
L/S 21/11/22

obays

total 5747.35

L/S: A.G.K.

4.6 K