

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 13 Dec 2022

Preliminary Advice

Vehicle No	: XE4928L	Accident Date	: 10/11/2022
Make	: SCANIA P370A4X2NZ	Policy No.	: SPCM1000000915
Assignment Date	: 24/11/2022	Excess	: S\$1,500.00
Date of Inspection	: 25/11/2022	Est. Duration of Repair	: 12
Inspection At	:SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	124,901.50
Revised Amount	:S\$	51,912.40
Check Items (Estimated)	:S\$	55,447.10
Total	:S\$	107,359.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	17,709.00
Salvage Value	:S\$	
Margin for Repair	:S\$	162,291.00

Remarks (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. (X) Other comments : Part by part repair, repairer unable to locate 2nd hand parts.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .