

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/01072/2022/EQ
DATE : 30-Nov-22
WIP : 52173

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/12/2022

YOUR INSURED VEH NO : SMS 9674 S

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR NG MUI CHU
ADDRESS : 10 KITCHENER LINK
#29-17
SINGAPORE 207225
TELEPHONE : HP +65 93682728
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : **SFM 754 T**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 16/5/2018
ENGINE NO : CVK 050959
CHASSIS NO : WAUZZZF55JA050342
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Nov-22
PLACE OF ACCIDENT : 243 BISHAN STREET 22, BLOCK 243,
SINGAPORE 570243 CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFM 754 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00	
5	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 754 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 529.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
8	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
10	FRONT BUMPER TOP COVER	1	\$ 143.00	
11	CAUTION SIGN STICKER	1	\$ 16.00	
12	AIR CONDITIONER STICKER	1	\$ 9.00	
13	LOCK CARRIER BRACKET	1	\$ 154.00	
14	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
15	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00	
16	FRONT PARKING AID SEAL RING	4	\$ 10.00	
17	FRONT FENDER - RH	1	\$ 1,189.00	
18	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	
19	FRONT FENDER BRACKET - RH	1	\$ 41.00	
20	FRONT FENDER RIVET	6	\$ 23.00	
SUB TOTAL SPARE PARTS		:	\$ 6,929.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFM 754 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE - RH	1	\$ 132.00	
22	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00	
23	FRONT FENDER CHROME TRIM - RH	1	\$ 171.00	
24	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	
25	FRONT WHEEL SPOILER	1	\$ 82.00	
26	FRONT WHEEL SPOILER END PLATE - RH	1	\$ 40.00	
27	FRONT WHEEL SPOILER STONE CHIP GUARD - RH	1	\$ 57.00	
28	FRONT WHEEL SPOILER TRIM BRACKET	1	\$ 27.00	
29	FRONT FENDER LEDGE COVER - LONG	1	\$ 40.00	
30	FRONT FENDER LEDGE COVER - RH SHORT	1	\$ 18.00	
31	HEADLIGHT - RH	1	\$ 8,416.00	
32	LIFT CYLINDER - RH	1	\$ 217.00	
33	LIFT CYLINDER BRACKET - RH	1	\$ 17.00	
34	LIFT CYLINDER CORRUGATED PIPE	1	\$ 100.00	
35	FRONT ALUMINUM RIM	1	\$ 1,889.00	
36	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
37	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 18,893.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	
GRAND TOTAL		:	\$ 25,145.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT