



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2300522

INV Date 30/01/2023

Reference CS/EQI22011857/Aqy3m4

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SLT 7627Z

Insured Veh. SMD 7787S

Claim No. DM22HO02042

Policy No.

Accident Date 05/11/2022

Inspection Date 06/12/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (8%)	12.80
Grand Total	172.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI22011857/Aqy3m4 Date: 30/01/2023 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 7787S	Veh. Inspected	SLT 7627Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM22HO02042	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	25/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NRE1610021390	Colour	SILVER
	Odometer	53163 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/11/2022	Inspection Date	06/12/2022
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 7627Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,249.60	565.00
1	REAR BUMPER REFLECTOR	NOT NECESSARY	79.50	-
1	REAR BUMPER SIDE RETAINER	CRACKED	105.40	45.00
1	REAR BUMPER BRACKET	NOT NECESSARY	85.20	-
1	TAIL LAMP	CRACKED	589.30	452.00
1	TAIL LAMP LOWER BRACKET	NOT NECESSARY	98.70	-
1	TAIL LAMP PANEL	NOT NECESSARY	245.80	-
1	REAR FENDER	TO REPAIR SEE LABOUR	974.30	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	147.60	-
1	REAR FENDER INNER TRIM	NOT NECESSARY	395.80	-
1	REAR FENDER AIR VENT	NOT NECESSARY	135.20	-
	LESS 25% DISCOUNT		-1,026.60	-265.50
			3,079.80	796.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	TAIL LAMP PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	180.00	-
			420.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,200.00	250.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	400.00
	TUFF COAT.		150.00	20.00
	WIRING CHECK ON TAILAMP.		100.00	30.00
	REMOVE AND REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	200.00	-

Report Ref No. CS/EQI22011857/Aqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	50.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
			3,380.00	750.00
GRAND TOTAL			6,879.80	1,576.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/EQI22011857/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/11/2022 14:54 (SGT)
Reported by	Both
Date of Accident	05/11/2022 16:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	EASTPOINT MALL BASEMENT CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT7627Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TEO TIAT CHYE
NRIC No	S0014757E
Email Address	IVYINET888@GMAIL.COM
Mobile Phone No	(Phone) +65-90177048
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Axio
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM110159381704

DRIVER

Name of Driver	TEO TIAT CHYE
NRIC No	S0014757E
Date Of Birth	17/10/1948
Occupation	Indoor



Date Of Driving Pass	27/11/1971
Driving experience	51 YEARS
Gender	Male
Mobile Number	(Phone) +65-90177048
Alt. Phone Number	-
Email Address	IVYINET888@GMAIL.COM
Address	34 TANAH MERAH KECHIL ROAD #12-29
Address complement	-
Postcode	465560
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	PASSENGER
Gender	Male

PASSENGER 2

Name	PASSENGER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD7787S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LEE LEH KHENG
NRIC No	S1237958G
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

The incident took place at Eastpoint Mall (Simei St 3)
Carpark level Basement one on 5 November 2022 around 4:50 PM.

When I was about to leave the Mall, I exited my car SLT 7627Z
from the parking lot (located beside the left lane) by turning left
and kept to the left lane. At that moment, there was a
black car (Mazda SMM1992H) reversing to park his car about
three parking lots away from my original parking lot which was
also located beside the left lane. I stopped my car and waited
for the driver to reverse his car into the parking lot. While my
car was stationary, an oncoming red Hyundai Elantra car
No. SMD 7787S was driving past from an opposite direction (on
the right lane^{hit} and scratched the right side of my car.
The lady driver of the red Hyundai Elantra SMD 7787S was Nidun
Lee Leh Kheng ID S1237958G. (B)

Note: left lane for car moving to the carpark exit
right lane for car moving from carpark entrance into the carpark

Reported By: Too Tiat Chye
S0014757E

X B

A

vehicle A SLT 7627Z


vehicle B SMD 7787S


SKETCH PLAN

IMPORTANT NOTICE


1. Please report ~~correctly~~ the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

 7/11/2022
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



SN0922B

1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 7627Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 7627Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 7627Z

RE-INSPECTION

