

ASS. REC. BY:

REF:

CTW 22011858/K^{np3}

C

Menneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Tailgate jammed, car not ready

13/12 11Pm @ 5600 Cnh (Red @ 8010.70, 59%)

Veh No:

SML13054

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Eclipse Cross

Wagon

C.C

1499

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

62281

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMAXTGK1WJZ002939

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/11/22

D.O.I.

25/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1) 16/12 Menneth

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / L.B.I. (\$

5600

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MITSUBISHI ECLIPSE CROSS

Engine/Chassis No.:

Date of accident:


Damaged area: Rear

Date: 25/11/2022

Claim Type: TP

VRN: SML1305Y

Not Notified
 1/1/2023 \$5600/-
 Recovery After Paim
 6 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper <i>348</i>	<i>BT</i> 1	\$ 1,154.00	\$ 1,154.00	
2	Rear bumper lower <i>152</i>	<i>BT</i> 1	\$ 547.00	\$ 547.00	
3	Rear bumper reflector lamp <i>0163</i>	<i>als my car</i> 2	\$ 233.00	\$ 466.00	
4	Rear bumper lower silver garnish <i>Dir/mg cm</i>	2	\$ 189.00	\$ 378.00	
5	Rear bumper reflector inner bracket	<i>R</i> 2	\$ 36.00	\$ 72.00	
6	Rear bumper side retainer	<i>R</i> 2	\$ 65.00	\$ 130.00	
7	Rear bumper reinforcement <i>266</i>	<i>BT</i> 1	\$ 894.00	\$ 894.00	
8	Rear bumper impact absorber LH/RH <i>093</i>	<i>CM</i> 2	\$ 115.00	\$ 230.00	
9	Rear bumper tow cover	<i>R</i> 1	\$ 41.00	\$ 41.00	
10	End panel upper <i>473</i>	<i>BT</i> 1	\$ 488.00	\$ 488.00	
11	End panel top garnish	<i>my dir</i> 1	\$ 177.00	\$ 177.00	
12	End panel lower	<i>R</i> 1	\$ 296.00	\$ 296.00	
13	Tailgate <i>984</i>	<i>BT</i> 1	\$ 1,959.00	\$ 1,959.00	
14	Rear windscreen moulding <i>95</i>	<i>me</i> 1	\$ 135.00	\$ 135.00	
15	Floor panel tools holder	<i>R</i> 1	\$ 395.00	\$ 395.00	
16	Tailgate weatherstrip	<i>Ref</i> 1	\$ 189.00	\$ 189.00	
17	Tailgate lock <i>181.90</i>	<i>Ref</i> 1	\$ 312.00	\$ 312.00	
18	Tailgate lock striker	<i>R</i> 1	\$ 75.00	\$ 75.00	
19	Tailgate inner trimboard <i>345</i>	<i>my CM</i> 1	\$ 577.00	\$ 577.00	
20	Rear exhaust assy <i>785.20</i>	<i>Ref</i> 1	\$ 1,138.00	\$ 1,138.00	
21	Rear exhaust assy mounting	<i>R</i> 2	\$ 45.00	\$ 90.00	
22	Rear exhaust assy heatshield	<i>R</i> 1	\$ 167.00	\$ 167.00	
23	Rear bumper reinforcement bracket	<i>R</i> 2	\$ 49.00	\$ 98.00	
24	Keyless antenna <i>162</i>	<i>CM</i> 1	\$ 215.00	\$ 215.00	
Subtotal				\$ 10,223.00	
List discount				10.00%	
Total				\$ 9,200.70	

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor <i>Ref/SH</i>	1	\$ 280.00	\$ 280.00
2	Rear bumper clip <i>me</i>	12	\$ 5.50	\$ 66.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

3	End panel top garnish clips	8	\$ 5.50	\$ 44.00
4	Reverse camera	1	\$ 480.00	\$ 480.00
5	Tailgate inner trimboard clip	10	\$ 5.50	\$ 55.00
6	End panel sealant	1	\$ 100.00	\$ 100.00
7	Rear licence plate and frame	1	\$ 55.00	\$ 55.00
8	Rear windscreen sealant	1	\$ 80.00	\$ 80.00
9	Sundries	1	\$ 50.00	\$ 50.00
			Total	\$ 1,210.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer.	1	\$ 200.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,200.00

Estimate Grand Total	\$ 13,610.70
-----------------------------	---------------------

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____