

Faster
memory
speedPrecision
touchpad

• Intel® Celeron® processor N4020

• Intel® UHD Graphics

• 4 GB DDR4 Memory

ASS. REC. BY:

REF: CTZ 22011858/K9

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SML13054 Yr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Eclipse Coss c.c. 1499

Colour:

M. Brown

A/C: Insured / Std / NI / NA

Sp. Reading

62281

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMAXTGK1WJE002939

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Blm or

Tyre Size:

F:

225/55R18

R:

BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/11/22

D.O.I.

25/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tailgate jammed, CST not ready

Time, File Pass to?



Prel. Report

Time, File Return to?



Final Report

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Format:

Sum / I.B.I. (\$

TOTAL