



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 8698K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT MUDGUARD	CRACKED	49.00	49.00
1	FENDER INNER	BROKEN	52.00	52.00
1	FENDER REAR	NOT NECESSARY	52.00	-
1	HANDLEBAR	BENT	58.00	58.00
1	HANDLE BRACKET	BENT	55.00	55.00
1	HANDLEBAR COVER	NOT NECESSARY	42.00	-
1	LAMP STAY	BENT	95.00	95.00
1	SET FORK UNDER BRACKET (FORK TUBE & FORK SPRING)	BENT	380.00	380.00
1	EXHAUST COVER	NOT NECESSARY	36.00	-
1	HEADLIGHT COMPLETE	CRACKED	240.00	240.00
1	COVER FRONT	CUT	48.00	48.00
1	FRONT LEFT SIGNAL COMPLETE	DISTORTED	42.00	42.00
1	COVER FRONT 2 BUTTON	CUT	40.00	40.00
1	L/S BODY COWLING	CUT	75.00	75.00
1	R/S BODY COWLING	CUT	75.00	75.00
1	L/S PANEL 1	DEFORMED	45.00	45.00
1	LEG SHIELD ASSY	CUT	55.00	55.00
1	CENTER COVER (OIL TANK)	NOT NECESSARY	55.00	-
1	L/S COVER 3 CENTER	CRACKED	60.00	60.00
1	L/S COVER 1 REAR	CUT	65.00	65.00
1	UNDER SKID PLATE	NOT NECESSARY	65.00	-
1	L/S MOLE SIDE COVER	CUT	40.00	40.00
1	R/S MOLE SIDE COVER	CUT	40.00	40.00
1	L/S FOOTREST BOARD	CUT	55.00	55.00
1	R/S FOOTREST BOARD	BROKEN	55.00	55.00
1	ARI BOX COVER	CUT	60.00	60.00
1	FRONT BRAKE DISC	BENT	75.00	75.00
1	FRONT WHEEL SHAFT	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-204.90	-179.90
			1,844.10	1,619.10

Report Ref No. CS/SMR22011867/Gvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>SPECIAL NETT ITEMS</u></b>	NECESSARY		
	CARGO BOX (SN)		210.00	180.00
			210.00	180.00
	<b><u>LABOUR</u></b>			
	TOW-TYPE COMPOUND.		60.00	50.00
	REFORM CHASSIC.		400.00	200.00
	LABOUR CHARGE FOR PART REPLACEMENT.		400.00	350.00
			860.00	600.00
<b>GRAND TOTAL</b>			<b>2,914.10</b>	<b>2,399.10</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,399.10</b>

Report Ref No. CS/SMR22011867/Gvy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.