

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
ı	UNITED OVERSEA	AS INSURANCE LTD	Ref:	CS/UOI22011873/Uny3m4	
	146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Date:	27/12/2022	
			Code:	UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
l	Insured Veh.	GBL 7901S	Veh. Inspected	PC 2321E	
I	Policy No.		Coverage (\$)	0.00	
	Claim No.	M12D00072212	Excess (\$)	0.00	
	Assign From	KATIE LEE	Assign Date	25/11/2022	
2. Vehicle Particulars & Condition					
I	Make & Model	MITSUBISHI ROSA 4.9	c.c	4899	
I	Engine No.	HIDDEN	Year of Reg.	2013	
(Chassis No.	BE63DJF10146	Colour	WHITE	
	Odometer	373730 KM	Steering	IN ORDER	
I	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
I	R/H Front Tyre	7.00 R16	FALKEN	6 mm	
I	L/H Front Tyre	7.00 R16	FALKEN	6 mm	
l	R/H Rear Tyre	7.00 R16 (D/D)	PIRELLI	6/6 mm	
I	L/H Rear Tyre	7.00 R16 (D/D)	PIRELLI	6/6 mm	
4. Description of Damages					
-	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
l l	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/11/2022	Inspection Date	02/12/2022	
:	Survey held at AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM)			AIM)	
		23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
l l	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				