

Auto Insure Pte. Ltd. 6 Marsiling Lane Singapore (739145) E: claims01@autoinsure.com.sg W: www.autoinsure.com.sg T: 3157 2626 F: 6368 0081

GST No.: 201437380M

Page No.1

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

## AUTOMOBILE ASSESSMENT REPORT

Our Ref: SNG2979K (CK)

Your Ref: SHC3704Y

25-Nov-22

Date: ATTENTION: MOTOR CLAIMS DEPT motor.survey@axa.com.sg Email:

AXA INSURANCE PTE LTD

8 Shenton way #27-01/02 AXA Tower Singapore 068811

: SNG2979K

: HYUNDAI AE IONIQ HEV 1.6 DCT Assessed Vehicle No Car Make and Model

: 24-Nov-22

We have carried out a physical assessment of SNG2979K at our workshop Auto Insure Pte Ltd

sustained damages to the RH portion of the vehicle.

At the time of the inspection observed that this vehicle had sustained damages to the FRONT RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

L/S

Estimated Amount 5,941.16 \$ Adjusted Amount

Est. Repair Days

Pursuant to your instruction, we have NOT AUTHORIZED repair.


The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.



Our Ref: SNG2979K Your Ref: SHC3704Y

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKS	SHOP	
1 2	1	FRONT DOOR RH / GT  FRONT DOOR LOWER GARNISH RH / CMA		\$ 110.10 🗸	1,655.50 252.50	<b>/</b>
3	1	REAR DOOR RH X Super		REPAIR		
5	1 1	REAR FENDER RH X		REPAIR REPAIR		
6	1	REAR DOOR LOWER GARNISH RH		\$ 125.30 ✓	195.32	
7	1	SIDE SKIRT RH / CM		\$	375.85	<b>~</b>
8	1	FRONT FENDER RH / Mc.		\$ 588.80 ✓	753.34	
9	1	FRONT HYUNDAI WHEEL CAP RH		\$	185.30	<b> </b>
10	1	REAR HYUNDAI WHEEL CAP RH	<b>-</b> .	\$	185.30	<b> </b>
			SUB TOTAL	\$	3,603.11	322
			LESS 20%	\$	720.62	-209
			TOTAL AMOUNT	\$	2,882.49	258

Our Ref: SNG2979K Your Ref: SHC3704Y

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP		
		-		-		
			SUB TOTAL	\$		
			TOTAL PARTS COST	\$ 2,882.49		

Our Ref: SNG2979K Your Ref: SHC3704Y

S/NO	DESCRIPTION			EST. BY WORKSHOP	
	LABOUR & PAINTS TO REMOVE THE AFFECTED PARTS & FITTINGS	Secretar Recognition and			
1	BEAT & RESHAPE THE AFFECTED AREAS AND AND COMPONE		\$	1,200.00	400
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEM	15 & PUFFY ON PARTS REPLACED	\$	1,200.00	1/00
3	TO PERFORM ANTI-RUST TREATMEN	NT ON AFFECTED AREAS	\$	100.00	60
4	SUNDRIES (SAND PAPER, WEI	LDING WIRE ETC.)	\$	60.00	X /
5	TO VACUUM, WAXING	& CLEAN	\$	60.00	XIM
6	TO PERFORM WATER SEEPAGE TEST	ON REPAIRED PORTIONS	\$	50.00	$\times I$
		TOTAL BEFORE GST	\$	5,552.49	
		GST 7%	\$	388.67	1560
		TOTAL (PARTS & LABOUR):	\$	5,941.16	

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

4140.92

Our Workshop has agreed to undertake the job at a <u>sum of \$ 5,941.16</u> for lump sum with the third party insurance.

L/S - 3312.73 = 3300

Yours Faithfully,

Jason Heng Claims Director

4 Days.

(uppm repri
After supri photos.

Guo Qiap

82880282

25/1/22

LKK Auto Consultant	s hence notify
the Repairer of the to	How ra:
<ul> <li>To resurvey !-' 'e'-!</li> </ul>	con, coming
• To de pie	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
• P	
o Ti	Ziz@d*c
• h)	2007
* (*	and
	- Ci - Limpany
Ackir. Acc. j	
Signature:	
Date:	