

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

LKK Auto Centre Singapore notify

the Reparer of the vehicle

ESTIMATE NO. : EST2211-638

To result in DATE : 24-Nov-2022

Parts POLICY NO. : AUTOGEN P10667726R00

VEHICLE REG. NO. : SMR1102J

VEHICLE MAKE : HONDA FIT 1.3GF CVT

is subject to final approval from Insurance Company

FOR SURVEYOR

Acknowledged by Reparer

Signature:

Date:

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Door RH <i>/ bne</i>	1	\$ 980.00	\$ 980.00 ✓
2	Rear Door Power Regular Assy RH <i>? BT</i>	1	\$ 200.00	\$ 200.00 ✓
3	Rear Door Sash RH <i>X bne</i>	1	\$ 80.00	\$ 80.00
4	Rear Door Outer Weatherstrip RH <i>X / bne</i>	1	\$ 80.00	\$ 80.00
5	Rear Door Inner Rubber Seal RH <i>X</i>	1	\$ 80.00	\$ 80.00
6	Rear Door Frame Moulding (Black Sticker) RH <i>/ bne</i>	1	\$ 40.00	\$ 40.00 ✓
7	Rear Wheel Bearing RH <i>? X nn</i>	1	\$ 480.00	\$ 480.00
Total Spare Parts				\$ 1,940.00
SPECIAL NETT				
8	Rear Door New Sealant <i>X nn</i>	1	\$ 40.00	\$ 40.00
9	Rear Rim RH <i>/ Cut</i>	1	\$ 480.00	\$ 480.00 250 ✓
Total Special Nett				\$ 480.00
LABOUR				
10	Spray Paint Rear Bumper, Fender RH, Frt and Rear Door RH	1	\$ 1,000.00	\$ 1,000.00 800 ✓
11	Replace & Refit Affected Accident Parts	1	\$ 800.00	\$ 800.00 200 ✓
12	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00 60 ✓
13	Remove, Refit and Replace Rear Undercarrier RH	1	\$ 180.00	\$ 180.00 ? X ✓
14	Computerized Wheel Alignment	1	\$ 70.00	\$ 70.00 60 ✓
15	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 X an ✓
Total Labour				\$ 2,160.00
Amount Before Excess				\$ 4,580.00 1120
Add GST @ 7%				320.60
Total Amount Payable				\$ 4,900.60

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

4 Days.
part by part.
before paint photos.
Gino Qianp. - 82880282
29/11/22.

P/P - 2346