



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHUA ENG CHUAN BLK 403D FERNVALE LANE #05-151 SINGAPORE 794403 Contact No Mobile: 97682720	Cust No/Name /CHUA ENG CHUAN Reg No/Reg Date SMK4212S / 09/04/201 Date In/Mileage 25/11/2022/ 81096 Chassis No GF7W0600457 Engine No 4J11AC0429 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/11/2022/ 17:08	REN	979 / Renemer	Ramirez Bag 12925
Description of Goods / Services					Qty Unit Price Disc% Amount
Z TEXT ACCIDENT ON 25/11/2022 ALONG SUNTEC CITY ROUNDABOUT OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP#: SMU1807T TP INS: ALLIANZ					
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK BY MUT AND CLEAR TROUBLE CODE					✓ 280.00
A 54900099 TO CHECK WIRING AND ELECTRICAL SYSTEM					✓ 80.00
E PNT88000 TO REPLACE RH HEADLAMP,FRONT BUMPER,CLIPS,BRACKETS,RH CHROME GARNISH, RH FOG LAMP & COVER,EXTENSION BPR,REINFORCEMENT,RH BPR & ARCH MLDG,ETC STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					640 1280.00
E PNT98000 SPRAY PAINTING ON RHF ACCIDENT AFFECTED AREAS (FRONT BUMPER,RHF FENDER)					1100 1650.00
B WHEELALIGNMENT120L To Conduct Computerize Full Wheel Alignment					x 180.00
M SUNDRY TO APPLY ANTI-CORROSION ON AFFECTED AREAS					80 100.00
M SUNDRY SUNDRIES					20 50.00
M RH,HEADLAMP ASSY					1.00 1967.00 00.00 ? 1967.00
M FACE,FR BUMPER					1.00 1023.00 00.00 dl 1023.00
M CLIP,ENG ROOM COVER					25.00 2.00 00.00 nel 50.00
M CLIP,BUMPER					5.00 3.00 00.00 nel 15.00
M LH SIDE BRACKET,FR BUMPER					1.00 18.00 00.00 x 18.00
M RH SIDE BRACKET,FR BUMPER					1.00 18.00 00.00 nel 18.00
M RH SIDE GARNISH,FR BUMPER					1.00 49.00 00.00 x 49.00
M RH UPR GARNISH,FR BUMPER					1.00 222.00 00.00 ant 222.00
M RH LWR GARNISH,FR BUMPER					1.00 113.00 00.00 ant 113.00
M RH FOG GARNISH,FR BUMPER					1.00 48.00 00.00 dl 48.00
M RH LAMP ASSY,FOG,FR					1.00 352.00 00.00 ? 352.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHUA ENG CHUAN BLK 403D FERNVALE LANE #05-151 SINGAPORE 794403 Contact No Mobile: 97682720	Cust No/Name /CHUA ENG CHUAN Reg No/Reg Date SMK4212S / 09/04/201 Date In/Mileage 25/11/2022/ 81096 Chassis No GF7W0600457 Engine No 4J11AC0429 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/11/2022/ 17:08	REN	979 / Renemer	Ramirez Bag 12925

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EXTENSION,FR BUMPER	1.00	515.00	00.00	515.00
M REINFORCEMENT,FR BUMPER	1.00	498.00	00.00	498.00
M BAR,FR BUMPER GUARD	1.00	131.00	00.00	131.00
M RH MOULDING,FR BUMPER	1.00	102.00	00.00	102.00
M RH MOULDING,FR WHEEL ARCH	1.00	162.00	00.00	162.00
M RH SHIELD,FR WHEELHOUSE	1.00	166.00	00.00	166.00
M CLIP,RR BUMPER	10.00	3.00	00.00	30.00
M TANK,WINDSHIELD WASHER	1.00	88.00	00.00	88.00
M SENSOR,W/SHLD WASHER TANK	1.00	115.00	00.00	115.00

SURVEYOR NAME: Tanfilin 97495749/62503561SURVEYOR SIGNATURE: [Signature]DATE: 29/11/22 @ 10:00amREMARKS: Resurvey before paintTanfilin @ Khantokan04 days

MV: 810SK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Authorized signatory and company stamp

Nett 9,302.00
7% GST on 9302.00 651.14
Total Payable 9,953.14

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.