



CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHUA ENG CHUAN	Cust No/Name	/CHUA ENG CHUAN
BLK 403D FERVALE LANE	Reg No/Reg Date	SMK4212S / 09/04/201
#05-151	Date In/Mileage	05/12/2022/ 81638
SINGAPORE 794403	Chassis No	GF7W0600457
Contact No Mobile: 97682720	Engine No	4J11AC0429
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	06/12/2022/ 09:05	REN	979 / Renemer Ramirez Bag	12925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 25/11/2022 ALONG SUNTEC CITY ROUNDABOUT								
OWNER CLAIMING THIRD PARTY								
LOSS OF RENTAL								
TP#: SMU1807T TP INS: ALLIANZ								
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK BY MUT AND CLEAR TROUBLE CODE						280.00
A	54900099	TO CHECK WIRING AND ELECTRICAL SYSTEM						80.00
E	PNT88000	TO REPLACE RH HEADLAMP,FR BUMPER,CLIPS,RH BRACKET,RH CHROME GARNISH, RH FOG LAMP COVER,RH BPR MLDG,RHF WHEEL ARCH MLDG,WASHER TANK,RIVETS. STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS						640.00
E	PNT98000	SPRAY PAINTING ON RHF ACCIDENT AFFECTED AREAS (FRONT BUMPER,RHF FENDER)						1100.00
M	SUNDRY	TO APPLY ANTI-CORROSION ON AFFECTED AREAS						80.00
M	SUNDRY	SUNDRIES						20.00
Z TEXT								
FINALIZATION								
NO. OF TOTAL REPAIR DAYS - 4 DAYS								
ATTENTION TO MR. MOHD TAUFIKH								
X	FACE,FR BUMPER				1.00	1023.00	00.00	1023.00
X	CLIP,ENG ROOM COVER				25.00	2.00	00.00	50.00
X	CLIP,BUMPER				5.00	3.00	00.00	15.00
X	RH SIDE BRACKET,FR BUMPER				1.00	18.00	00.00	18.00
M	RH SIDE GARNISH,FR BUMPER				1.00	49.00	00.00	49.00
X	RH UPR GARNISH,FR BUMPER				1.00	222.00	00.00	222.00
X	RH LWR GARNISH,FR BUMPER				1.00	113.00	00.00	113.00
X	RH FOG GARNISH,FR BUMPER				1.00	48.00	00.00	48.00
X	RH MOULDING,FR BUMPER				1.00	102.00	00.00	102.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



MITSUBISHI MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHUA ENG CHUAN	Cust No/Name	/CHUA ENG CHUAN
BLK 403D FERNVALE LANE	Reg No/Reg Date	SMK4212S / 09/04/201
#05-151	Date In/Mileage	05/12/2022/ 81638
SINGAPORE 794403	Chassis No	GF7W0600457
Contact No Mobile: 97682720	Engine No	4J11AC0429
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	06/12/2022/ 09:05	REN	979 / Renemer Ramirez Bag	12925

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH MOULDING,FR WHEEL ARCH	1.00	162.00	00.00	162.00
X CLIP,RR BUMPER	10.00	3.00	00.00	30.00
M TANK,WINDSHIELD WASHER	1.00	88.00	00.00	88.00
M RIVET,ENG ROOM COVER	4.00	4.00	00.00	16.00
M RH,HEADLAMP ASSY	1.00	1967.00	00.00	1967.00

Estimate

Confirm & accepted by

	Nett	6,103.00
7% GST on		427.21
	<b>Total Payable</b>	<b>6,530.21</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.