







CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHUA ENG CHUAN BLK 403D FERNVALE LANE #05-151 SINGAPORE 794403 Contact No Mobile: 97682720	Cust No/Name /CHUA ENG CHUAN Reg No/Reg Date SMK4212S / 09/04/201 Date In/Mileage 25/11/2022/ 81096 Chassis No GF7W0600457 Engine No 4J11AC0429 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	25/11/2022/ 17:08	REN	979 / Renemer	Ramirez Bag 12925

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EXTENSION,FR BUMPER	1.00	515.00	00.00	515.00
M REINFORCEMENT,FR BUMPER	1.00	498.00	00.00	498.00
M BAR,FR BUMPER GUARD	1.00	131.00	00.00	131.00
M RH MOULDING,FR BUMPER	1.00	102.00	00.00	102.00
M RH MOULDING,FR WHEEL ARCH	1.00	162.00	00.00	162.00
M RH SHIELD,FR WHEELHOUSE	1.00	166.00	00.00	166.00
M CLIP,RR BUMPER	10.00	3.00	00.00	30.00
M TANK,WINDSHIELD WASHER	1.00	88.00	00.00	88.00
M SENSOR,W/SHLD WASHER TANK	1.00	115.00	00.00	115.00

Estimate

SURVEYOR NAME : Tanfikha 97495749 / 62503561

SURVEYOR SIGNATURE : [Signature]

DATE : 29/11/22 @ 10:00am

REMARKS : Resurvey before paint  
Tanfikha @ Khantoran  
04 days

MV: 810SK

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Confirm & accepted by			
	7% GST on	Nett 9302.00	9,302.00 651.14
		<b>Total Payable</b>	<b>9,953.14</b>
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.