

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TASHA BIN ABU BAKAR
BLK 486 PASIR RIS DRIVE 4 #03-489
SINGAPORE 510486

Contact : 93862740

TAX INVOICE TP Allianz

Repair Code : CLM15742

Date in : 25/11/2022

Vehicle Num. : SKH6599C

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305085532/1NZX816092

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	666.70	✓ 666.70
REAR BOOTLID 'LOGO' EMBLEM <i>new</i>	1	53.90	✓ 53.90
REAR BOOTLID HINGES L/R <i>new</i>	2	59.50	+ 119.00
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	106.40	✓ 106.40
REAR BOOTLID MECHANISM LOCK STRIKER <i>new</i>	1	43.55	+ 43.55
REAR BOOTLID OUTER GARNISH <i>new</i>	1	181.70	✓ 181.70
REAR BOOTLID RUBBER GUIDE STOPPER L/R <i>new</i>	2	43.90	+ 87.80
REAR BOOTLID WEATHER STRIP <i>new</i>	1	194.20	✓ 194.20
REAR BUMPER <i>Dented</i>	1	495.70	✓ 495.70
REAR BUMPER BRACKET L/R <i>new</i>	2	69.90	✓ 139.80
REAR BUMPER END SEAL COVER L/R <i>new</i>	2	55.50	+ 111.00
REAR BUMPER REFLECTOR L/R <i>new</i>	2	92.00	✓ 184.00
REAR BUMPER SIDE CORNER BRACKET L/R <i>new</i>	2	39.80	+ 79.60
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	102.80	✓ 205.60
REAR CENTER SPONGE <i>new</i>	1	146.40	+ 146.40
REAR END PANEL <i>Dented</i>	1	696.30	✓ 696.30
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	222.80	125 222.80
REAR EXHAUST GASKET <i>new</i>	1	61.10	+ 61.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TASHA BIN ABU BAKAR
 BLK 486 PASIR RIS DRIVE 4 #03-489
 SINGAPORE 510486

Contact : 93862740

TAX INVOICE

Repair Code : CLM15742

Date in : 25/11/2022

Vehicle Num. : SKH6599C

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305085532/1NZX816092

REAR EXHAUST RUBBER MOUNTING	3	63.90	+	191.70
REAR EXHAUST SILENCER BOX	1	771.10	+	771.10
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	247.90	+	495.80
REAR LH SPARE TYRE TOP SPONGE	1	190.00	—	190.00
REAR NUMBER PLATE	1	25.00	+	25.00
REAR NUMBER PLATE LAMP L/R	2	65.40	+	130.80
REAR RH SPARE TYRE TOP SPONGE	1	237.10	✓	237.10
REAR SPARE TYRE INNER TOP CARDBOARD COVER	1	172.10	✓	172.10
REAR TAILLAMP BACK RUBBER GASKET L/R	2	61.10	40	122.20
REAR TAILLAMP L/R	2	380.00	590	760.00
REAR TAILLAMP PANEL L/R	2	231.20	+	462.40
Subtotal before discount				7,353.75
Percentage discount 25%				1,838.44
Sub-total 1				5,515.31
REAR BOOTLID OUTER GARNISH CLIPS - SET	1	30.00	20	30.00
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	20.00	+	40.00
REAR BUMPER REVERSE SENSOR	1	250.00	20	250.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TASHA BIN ABU BAKAR
BLK 486 PASIR RIS DRIVE 4 #03-489
SINGAPORE 510486

Contact : 93862740

TAX INVOICE

Repair Code : CLM15742

Date in : 25/11/2022

Vehicle Num. : SKH6599C

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305085532/1NZX816092

REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>mu</i>	1	30.00	<i>10</i> 30.00
REAR END PANEL SEALANT <i>mu</i>	1	80.00	<i>60</i> 80.00
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET <i>mu</i>	2	30.00	<i>+</i> 60.00
REAR NUMBER PLATE HOLDER <i>mu</i>	1	50.00	<i>+</i> 50.00
REAR TAILLAMP CLIPS L/R - SET <i>mu</i>	2	30.00	<i>20</i> 60.00
<i>340</i> Subtotal before discount			650.00
Percentage discount 0%			0.00
Sub-total 2			650.00
Parts-total			6,165.31

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,980.00

Parts & Labour Total

9,145.31

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.***

page 3

Admin C
1/528/11/22

06 days

total: 5328.87

L/s: 42k