

ASS. REC. BY:

REF:

AIG/22011893/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S4C5268B

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

185241

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU703092186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Wanki

195/65R15

R: Bajan

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

24/11/22

D.O.I.

24/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

191 N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA not ready

16/12

14769.50 Cash

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

: Fines

: Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5268B**AAD2211-***Not Authored
Primary B4 point*

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

24 NOV 2022**SHC5268B**

JTDB3FU703092186

200303878K

TOYOTA

PRIUS **GEN 4**

24/11/2022

SKV2756T/AIG

09/10/2020

PART	LIST
1 HOOD SUB-ASSY	\$ R 983.10 X
1 INSULATOR, HOOD	\$ Sn 410.90 X
1 HINGE ASSY, HOOD, LH	\$ R 58.90 X
1 HINGE ASSY, HOOD, RH	\$ R 58.90 X
1 FENDER SUB-ASSY, FRONT LH	\$ R 977.80 ✓
1 LINER, FRONT FENDER, LH	\$ Tn 210.30 ✓
1 EMBLEM, SIDE PANEL	\$ Rn 54.60 ✓
1 COVER, FRONT BUMPER	\$ Tn 521.00 ✓
1 MOULDING, FRONT BUMPER SIDE, LH	\$ Rn 95.60 ✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 716.60 ✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ R 246.10 X
1 ABSORBER, FRONT BUMPER, LOWER	\$ CM 132.70 ✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ CM 80.20 ✓
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ Dn 82.30 ✓
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ Sn 241.90 X
1 EXTENSION, FRONT BUMPER, LH	\$ Sn 120.10 X
1 EXTENSION, FRONT BUMPER, RH	\$ Sn 120.10 X
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$ Sn 47.50 X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$ Sn 47.50 X
1 BRACKET, FRONT BUMPER SIDE, LH	\$ CM 59.30 ✓
1 BRACKET, FRONT BUMPER SIDE, RH	\$ Sn 59.30 X
1 COVER, FRONT BUMPER HOLE, RH	\$ Rn 30.20 ✓
1 BRACKET, HEADLAMP, LH	\$ CM 34.80 ✓
1 LAMP ASSY, FOG, LH	\$ CM 237.10 ✓
1 UNIT ASSY, HEADLAMP, LH	\$ CM 2,637.60 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ Dn 422.50 ✓
1 EMBLEM ASSY, MOULDING	\$ Rn 160.50 ✓

Trans-cab Auto Services Pte Ltd**AAD2211-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5268B

1	GRILLE, RADIATOR, LOWER NO.1	\$	<i>nd/dit</i> 178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	<i>na</i> 105.80	✓
1	CONDENSER ASSY, COOLER	\$	<i>na</i> 1,783.20	X
1	SUPPORT, RADIATOR, UPPER LH	\$	<i>na</i> 78.90	X
1	SUPPORT, RADIATOR, UPPER RH	\$	<i>na</i> 78.90	X
1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	<i>na</i> 377.10	X
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	<i>na</i> 245.10	X
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	<i>na</i> 245.10	X
TOTAL		\$	11,940.10	
25%		\$	2,985.03	
		\$	8,955.08	

Special Nett

1	FRT NUMBER PLATE WITH HOLDER	\$	<i>na</i> 140.00	X
1SET	BUMPER CLIP FRT	\$	<i>na</i> 95.00	<i>60.00</i>
1SET	FRNT BUMPER RETAINER CLIP	\$	<i>na</i> 85.00	X
4L	Radiator Coolant	\$	<i>na</i> 120.00	X
1	HOOD INSULATOR CLIP	\$	<i>na</i> 55.00	X
1	Engine Under Cover Clip	\$	<i>na</i> 60.00	X
1	FRT FENDER LINER CLIP	\$	<i>na</i> 65.00	✓
TOTAL		\$	555.00	
TOTAL PARTS		\$	9,510.08	

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *na* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,000.00 *5001*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *na* 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *na* 480.00 X

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5268B

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	Λ
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	301
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	5001
To Check Electrical Lighting Concerned.	\$		170.00	201
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X
TOTAL	\$		9,870.00	
Over All Total	\$		19,380.08	

(PART-BY-PART) Repair Days**04 DAYS****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5268B

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**PART**

- 1 BRACE SUB-ASSY, FENDER APRON, LH
- 1 WIRE, ENGINE ROOM MAIN
- 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1

SHC5268B

JTDKB3FU703092186

200303878K

TOYOTA

PRIUS GEN 4

24/11/2022

SKV2756T/AIG

09/10/2020

	LIST	
\$	<i>Ry</i> 292.10	✓
\$	<i>Tn</i> 7,323.90	✓
\$	<i>Rd</i> 3,772.50	✓
TOTAL \$	11,388.50	
25% \$	2,847.13	
\$	8,541.38	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHC5268B

Vehicle to be Exported: Yes

Intended Deregistration Date: 24 Nov 2022

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2020

Engine No.: 2ZR2H00815

Chassis No.: JTDKB3FU703092186

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,807.00

Original Registration Date: 09 Oct 2020

First Registration Date: 09 Oct 2020

Transfer Count: 0

Actual ARF Paid: \$14,530.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Oct 2028

PARF Rebate Amount: \$10,897.00

Intended COE Rebate Details

COE Expiry Date: 08 Oct 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$28,160.00

COE Rebate Amount: \$20,667.00

Total Rebate Amount: \$31,564.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Nov 2022

OK