

Tny3

REF:

CS/TM12201896/795

ASS. REC.BY: Taufik

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / MS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP'

Vehicle: IN / OUT

Date: _____ Person Contacted: Lim TS

Veh No:

SHB3815K

Yr Regn:

20171 Rec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / ① Taxi / Prime Mover /

Truck / Trailer or _____

Make:

Mynder 140

C.C.

1685

Colour

yellow

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No:

KMH LB414MAH099792

Gen. Cond: ① Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: ① NI / S/Rim / STD A/Rim or _____

Tyre Size:

F:

205/60R16

R:

2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28/11/22

Survey held at

Confort Layer

Des. of Damages: Frt / ① Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Taufikh finalised LS \$1650, 3 days. (Red \$4050, 71%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/01 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

Rep. Format:

MER-TP

Lump Sum / B.E. / P

1650

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/11/2022
Vehicle Reg. No.:	SHB3815R	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	15/12/2017
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU689974	Chassis No:	KMHLB41UMHU099992
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	3,949.86
Miscellaneous Items	11.00
Labour	1,740.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	5,700.86
+ GST 7.00% (S\$)	399.06
Nett Amount (S\$)	6,099.92

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB3815R/25/11/2022 11:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID	20.00	0.00	*2,609.80 FL _{Rx}
2	2		*BOOTLID HINGE RH / LH	20.00	0.00	*284.00 FL _{Rx}
3	1		*BOOTLID H EMBLEM	20.00	0.00	*63.10 FL _{new}
4	1		*BOOTLID CRDI EMBLEM	20.00	0.00	*52.40 FL _{new}
5	1		*BOOTLID COMFORTDELGRO EMBLEM	0.00	0.00	*30.00 F _{new}
6	1		*BOOTLID 65521111 EMBLEM	0.00	0.00	*30.00 F _{new}
7	1		*REAR BUMPER	20.00	0.00	*553.00 FL _{new}
8	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL _{new}
9	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL _?
10	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH	20.00	0.00	*71.20 FL _?
11	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL _{new}
12	1		*BOOTLID MOULDING	20.00	0.00	*85.00 FL _{cut}
13	1		*BOOTLID LOWER GARNISH	20.00	0.00	*227.90 FL _{cut}
14	1		*REVERSE SENSORS	0.00	0.00	*135.70 F _x
15	1		*BOOTLID I40 EMBLEM	20.00	0.00	*67.90 FL _{new}
Sub Total (\$\$)						4,888.40
- List Item Discount on L Items (\$\$)						938.54
Total Parts (\$\$)						3,949.86

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB3815R/25/11/2022 11:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Lim Tien Siong

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

7 420 900.00

2 SPRAY PAINTING

New

500 600.00

3 TUFF KOTE

New

X 60.00

4 R/I REVERSE SENSORS

New

X 120.00

5 TOWING FEE

New

✓ 60.00

Gross Labour Cost (S\$)

1,740.00

ComfortDelGro Engineering Pte Ltd/SHB3815R/25/11/2022 11:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 7749549
wp, 28/11/22 430pm
L/S Repair after repair
tanpin c (Lk Auto) car
2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

43 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 23.11.2022 11:14

Page : 1

Job: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5302068

JC NO: 305537741

Customer:

IS CITYCAB PTE LTD
OMER NO. 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

IDENTIFICATION CARD NO.


REGN NO: SHB3815R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 24.11.2022 21:15
YR OF MANU. 15.12.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU099992	COMPLETION DATE/TIME:

Incident Date: 24.11.2022
NATURE: 3P 24.11.2022

JOB DESCRIPTION

NO LABOR CODE
0010 PB
0020 23-01

DESCRIPTION
LUMPSUM REPAIR-SHB3815R TP
TOWING FEE



ISSUED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: SHB3815R LIMITS

Vehicle No.: SHB3815R

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard




JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

Date: <u>24-11-22</u> Time Received: <u>2250</u> ☐ New ☒ SPARK Kakis Name of Customer: <u>Mr Ng</u> Contact No.: <u>9010 9868</u> Vehicle No.: <u>SHB 3815 R</u> Make / Model / Colour: <u>I40</u> Email: _____		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
Location: <u>Sembawang Rd</u> 1. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	
0. Odometer Reading: _____ Fuel Level: ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E		6. Parts Replaced/Remarks: _____ _____ _____	
8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Fault ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi		11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested	

Job Attended

2. Tow Truck / Recovery Van: ☐ VRS ☒ QA ☐ GAO ☐ OTHERS
 Name of Driver: Hafiz
 Vehicle No.: YP 6632 G
 Time Dispatch: _____
 Time of Arrival: _____
 Time Completed: _____



: Cracked X : Dent
/ : Scratched O : Missing

Signature of Customer

Cash Invoice Details (if applicable)

3. Cash Invoice No.: _____

Customer Acknowledgement

I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupon, cash cards, spectacles, pen, etc.
 I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
 Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

4. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S C