

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22011900/AWY3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001404289

Claimant Vehicle No : SMQ8684E**Insured Vehicle No :** SKT3790Y

Date of Loss: 23/11/2022

Nature of Claim: TP

Claim No: 292270

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ8684E**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25511371

Reg. Date: 06/12/2019 (Man. Year: 2019)

Chassis No: MRHFC5650KT001182

Colour: Blue

Odometer: 61981 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car PriceCONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,402.03	1,643.12	758.91	31.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	930.00	720.00	43.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,052.03	2,573.12	1,478.91	36.50
+ GST 8.00/8.00% (S\$)	324.16	205.85	118.31	36.50
Nett Amount (S\$)	4,376.19	2,778.97	1,597.22	36.50

INSPECTION

Date of Assignment: 28/11/2022

Date Inspected: 28/11/2022 Inspected At:

BLK 3007 UBI ROAD 1

#01-434

SINGAPORE 408701

Repairer: KAI MOTOR TRADING (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR COST NOT CONCLUDE

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ8684E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	450.80 FL	*450.80 FL
2	1		*FRONT FENDER LAMP LH	Cut	675.90 FL	*675.90 FL
3	1		*FRONT FENDER LAMP MOULDING LH	Not Necessary	112.20 FL	*- FL
4	1		*FRONT FENDER LAMP LH	Not Necessary	74.30 FL	*- FL
5	1		*FRONT GRILLE	Cracked	214.50 FL	*214.50 FL
6	1		*FRONT HEAD LAMP LOWER GARNISH LH	Not Necessary	30.80 FL	*- FL
7	1		*FRONT BUMPER	Distorted	579.90 FL	*579.90 FL
8	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	19.80 FL	*- FL
9	12		*FRONT BUMPER CLIPS	Necessary	46.80 FL	*30.00 FL
10	1		*FRONT BUMPER FORD LAMP LH	Not Necessary	288.90 FL	*- FL
11	1		*FRONT BUMPER FORD LAMP GARNISH LH	Cut	102.80 FL	*102.80 FL
12	1		*FRONT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,661.70 2,053.90
					- List Item Discount on L Items 10.00/20.00% (\$\$)	259.67 410.78
					Total Parts (\$\$)	2,402.03 1,643.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	680.00	500.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	750.00	400.00
3	COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
Gross Labour Cost (\$\$)			1,650.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >