

BIFROST AUTO PTE LTD

Not Not have
Penny Bepain
9 days

614185.74

9 days

REPAIR ESTIMATE

DATE: 28-Nov-22

KMH2851CVK_{INS}

INSURANCE:

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 2017 D

Description	Qty	List Price	Amount
Frt Door(LH) 1797.20	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH)	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (LH)	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH)	1	\$ 153.70	\$ 153.70
Front Door Check (LH) SCR	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (LH)	1	\$ 385.60	\$ 385.60
Front Door Outer Handle (LH)	1	\$ 234.80	\$ 234.80
Front Door Mirror ASSY (LH)	1	\$ 1,691.70	\$ 1,691.70
Front Door Protector(LH)	1	\$ 186.20	\$ 186.20
Front Door Outer Moulding (LH)	1	\$ 110.10	\$ 110.10
Rear Door (LH)	1	\$ 2,147.90	\$ 2,147.90
Rear Door Rubber(LH)	1	\$ 280.00	\$ 280.00
Rear Door Outer Moulding(LH)	1	\$ 125.30	\$ 125.30
Rear Door Outer Handle (LH)	1	\$ 124.80	\$ 124.80
Rear Door Gear/Regulator(LH)	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH)	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy	1	\$ 306.40	\$ 306.40
Rear Door Hinge Upper (LH)	1	\$ 173.88	\$ 173.88
Rear Door Hinge Lower (LH)	1	\$ 170.50	\$ 170.50
Rear Door Check(LH)	1	\$ 85.92	\$ 85.92
Rear Door Protector(LH)	1	\$ 166.20	\$ 166.20
Door Centre Pillar Outer (LH) R-1 3764.90	1	\$ 3,764.90	\$ 3,764.90

Rocker Panel Outer Garnish	<i>me</i>	1	\$ 715.60	\$ 715.60	✓
Rocker Panel Outer	<i>R</i>	1	\$ 1,799.60	\$ 1,799.60	X
Rocker Panel Step Garnish (Front) (LH)	<i>in</i>	1	\$ 156.50	\$ 156.50	X
Rocker Panel Step Garnish(Rear)(LH)	<i>in</i>	1	\$ 178.30	\$ 178.30	X
Rear Bumper	<i>cm</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Side retainer (LH)	<i>dit</i>	1	\$ 85.80	\$ 85.80	✓
Rear Bumper Cover Clips	<i>me</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Side Under(LH)	<i>in</i>	1	\$ 123.10	\$ 123.10	X
Rear Fender(LH)	<i>R</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Fender SHIELD REAR PIECE (LH)	<i>in</i>	1	\$ 173.60	\$ 173.60	X
Rear Fender SHIELD Frt Piece (LH)	<i>in</i>	1	\$ 165.50	\$ 165.50	X
Rear Fender Air-Duct (LH)	<i>in</i>	1	\$ 87.30	\$ 87.30	X
Rear Fender Trim Board (LH)	<i>in</i>	1	\$ 788.75	\$ 788.75	X
Assy BSD Blind Spot Radar (LH)	<i>in</i>	1	\$ 1,784.40	\$ 1,784.40	X
SUB TOTAL				\$ 22,766.23	
LESS 20%				\$ 4,553.25	
DISCOUNTED TOTAL				\$ 18,212.98	
Front Door Comfort Logo (LH)	<i>me</i> SN	1	\$ 75.00	\$ 75.00	✓
Rear Door Comfortdelgro & Apps Sticker(LH)	<i>me</i> SN	1	\$ 80.00	\$ 80.00	✓
Rear Bumper Rubber Mat	<i>me</i> SN	1	\$ 50.00	\$ 50.00	✓
SUB TOTAL				\$ 205.00	
Labour Charge					
Panel Beating		1	\$2,000.00	\$2,000.00	1200
Spray Painting Charge		1	\$1,600.00	\$1,600.00	1200
Wiring Charge		1	\$100.00	\$100.00	300
Tuff Kote		1	\$100.00	\$100.00	900
Towing Charge	(Bill)	1	\$80.00	\$80.00	500
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	1000

11080.74

Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	501
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	601
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	601
Re-set Frt Power Window System	1	\$200.00	na \$200.00	X
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	601
Re-set Rear Power Window System	1	\$200.00	na \$200.00	X
Diagnostic & Resetting To Erase Fault Code	1 na	\$550.00	\$550.00	X
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	na \$550.00	X
TOTAL LABOUR			\$5,890.00	
ESTIMATE TOTAL			\$24,307.98	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com				

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: