



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22009310/Eny3m4-1

Date: 16/12/2022

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMC 7474A	<b>Veh. Inspected</b>	SMH 4861J
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	22/22/22/VP05/026255	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	28/11/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	BMW 318I	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	WBAPF720X0A794046	<b>Colour</b>	WHITE
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/45 R17	CONTINENTAL	4 mm
<b>L/H Front Tyre</b>	215/45 R17	CONTINENTAL	4 mm
<b>R/H Rear Tyre</b>	215/45 R17	CONTINENTAL	4 mm
<b>L/H Rear Tyre</b>	215/45 R17	CONTINENTAL	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/09/2022	<b>Inspection Date</b>	21/09/2022
<b>Survey held at</b>	40 Toh Guan Road East #01-67 Enterprise Hub		
<b>Repairer</b>	MASTER CAR SPRAY SERVICE		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------