

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22009310/Eny3-1

LONPAC INSURANCE BHD

Ref: ~~CS3/LPC22009310/En2y3~~

300 BEACH ROAD

Date: ~~21/09/2022~~ 28/11/2022

#17-04/07 THE CONCOURSESINGAPORE 199555

Code: LPC2

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

<b>Insured Veh.</b>	SMC 7474A	<b>Veh. Inspected</b>	SMH 4861J
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	22/22/22/V05/026255	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	<del>21/09/2022</del> 28/11/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

--

**5. General Information**

<b>Accident Date</b>	03/09/2022	<b>Inspection Date</b>	21/09/2022
<b>Survey held at</b>	40 Toh Guan Road East #01-67 Enterprise Hub		
<b>Repairer</b>	MASTER CAR SPRAY SERVICE		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--