

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2111- 644
DATE : 28-Nov-2022
POLICY NO. : FWD PNPV2022-00001218
VEHICLE REG. NO. : SJN5149E
VEHICLE MAKE : HYUNDAI HD AVANTE 1.6 ATO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper <i>X Repair</i>	1	\$ 680.00	\$ 680.00
2	Front Bumper Clips <i>X</i>	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH <i>X</i>	1	\$ 50.00	\$ 50.00
4	Front Bumper Retainer LH <i>X</i>	1	\$ 50.00	\$ 50.00
5	Front Reinforcement <i>?</i>	1	\$ 350.00	\$ 350.00
6	Front Sponge <i>?</i>	1	\$ 120.00	\$ 120.00
7	Front Grille Assy <i>X</i>	1	\$ 380.00	\$ 380.00
8	Front Lower Grille (Center) <i>X</i>	1	\$ 200.00	\$ 200.00
9	Front Support Panel <i>X</i>	1	\$ 620.00	\$ 620.00
10	Foglamp Garnish RH <i>X</i>	1	\$ 40.00	\$ 40.00
11	Foglamp Garnish LH <i>X</i>	1	\$ 40.00	\$ 40.00
12	Headlamp RH <i>?</i>	1	\$ 350.00	\$ 350.00
13	Headlamp LH <i>?</i>	1	\$ 350.00	\$ 350.00
14	Rear Bumper <i>Re</i>	1	\$ 700.00	\$ 700.00
15	Rear Bumper Clips <i>Re</i>	10	\$ 5.00	\$ 50.00
16	Rear Bumper Retainer RH <i>X</i>	1	\$ 50.00	\$ 50.00
17	Rear Bumper Retainer LH <i>X</i>	1	\$ 50.00	\$ 50.00
18	Rear Reinforcement <i>Re</i>	1	\$ 380.00	\$ 380.00
19	Rear Sponge <i>Re</i>	1	\$ 130.00	\$ 130.00
20	Rear Tail lamp RH <i>Re</i>	1	\$ 320.00	\$ 320.00
21	Rear Tail lamp LH <i>Re</i>	1	\$ 320.00	\$ 320.00
22	Rear Bootlip lamp RH <i>X</i>	1	\$ 250.00	\$ 250.00
23	Rear Bootlip lamp LH <i>X</i>	1	\$ 250.00	\$ 250.00
24	Rear Bootlid <i>Buc</i>	1	\$ 1,200.00	\$ 1,200.00
25	Rear Bootlid Lock <i>BT</i>	1	\$ 120.00	\$ 120.00
26	Rear Bootlid Rubber Seal <i>Re</i>	1	\$ 80.00	\$ 80.00
27	Rear Bootlid Outer Garnish <i>X</i>	1	\$ 80.00	\$ 80.00
28	Rear Hyundai Emblem <i>Re</i>	1	\$ 50.00	\$ 50.00
29	Rear Avante Emblem <i>Re</i>	1	\$ 50.00	\$ 50.00
30	End Panel <i>Buc</i>	1	\$ 550.00	\$ 550.00
31	End Panel Garnish <i>Re</i>	1	\$ 80.00	\$ 80.00

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111- 644

DATE : 28-Nov-2022

POLICY NO. : FWD PNPV2022-00001218

VEHICLE REG. NO. : SJN5149E

VEHICLE MAKE : HYUNDAI HD AVANTE 1.6 A

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Total Spare Parts				\$ 7,990.00
SPECIAL NETT				
32	Front License Plate With Casing / CPA	1	\$ 40.00	\$ 40.00
33	Rear License Plate With Casing / Cnt	1	\$ 40.00	\$ 40.00
34	Reverse Sensor / Mis	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
LABOUR				
35	Spray Paint (Front Bumper, Bonnet, Rear Bumper & Bootlid)	1	\$ 1,000.00	\$ 1,000.00
36	Remove and Refit Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00
37	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
38	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
39	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,210.00
Amount Before Excess				\$ 10,480.00
Add GST @ 7%				733.60
Total Amount Payable				\$ 11,213.60

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour

Amount Before Excess

Add GST @ 7%

Total Amount Payable

5 Days.

Imps in Repair / After repair photos

Guo Q: ang

8288 0282

28/11/22

Guo Q: ang @ HK Auto.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be resurveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: