

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111- 644

DATE : 28-Nov-2022

POLICY NO. : FWD PNPV2022-00001218

VEHICLE REG. NO. : SJN5149E

VEHICLE MAKE : HYUNDAI HD AVANTE 1.6 A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 680.00	\$ 680.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 50.00	\$ 50.00
4	Front Bumper Retainer LH	1	\$ 50.00	\$ 50.00
5	Front Reinforcement	1	\$ 350.00	\$ 350.00
6	Front Sponge	1	\$ 120.00	\$ 120.00
7	Front Grille Assy	1	\$ 380.00	\$ 380.00
8	Front Lower Grille (Center)	1	\$ 200.00	\$ 200.00
9	Front Support Panel	1	\$ 620.00	\$ 620.00
10	Foglamp Garnish RH	1	\$ 40.00	\$ 40.00
11	Foglamp Garnish LH	1	\$ 40.00	\$ 40.00
12	Headlamp RH	1	\$ 350.00	\$ 350.00
13	Headlamp LH	1	\$ 350.00	\$ 350.00
14	Rear Bumper	1	\$ 700.00	\$ 700.00
15	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
16	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
17	Rear Bumper Retainer LH	1	\$ 50.00	\$ 50.00
18	Rear Reinforcement	1	\$ 380.00	\$ 380.00
19	Rear Sponge	1	\$ 130.00	\$ 130.00
20	Rear Tail lamp RH	1	\$ 320.00	\$ 320.00
21	Rear Tail lamp LH	1	\$ 320.00	\$ 320.00
22	Rear Bootlip lamp RH	1	\$ 250.00	\$ 250.00
23	Rear Bootlip lamp LH	1	\$ 250.00	\$ 250.00
24	Rear Bootlid	1	\$ 1,200.00	\$ 1,200.00
25	Rear Bootlid Lock	1	\$ 120.00	\$ 120.00
26	Rear Bootlid Rubber Seal	1	\$ 80.00	\$ 80.00
27	Rear Bootlid Outer Garnish	1	\$ 80.00	\$ 80.00
28	Rear Hyundai Emblem	1	\$ 50.00	\$ 50.00
29	Rear Avante Emblem	1	\$ 50.00	\$ 50.00
30	End Panel	1	\$ 550.00	\$ 550.00
31	End Panel Garnish	1	\$ 80.00	\$ 80.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111- 644

DATE : 28-Nov-2022

POLICY NO. : FWD PNPV2022-00001218

VEHICLE REG. NO. : SJN5149E

VEHICLE MAKE : HYUNDAI HD AVANTE 1.6 A

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Total Spare Parts				\$ 7,990.00
	<u>SPECIAL NETT</u>			
32	Front License Plate With Casing	1	\$ 40.00	\$ 40.00
33	Rear License Plate With Casing	1	\$ 40.00	\$ 40.00
34	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
	<u>LABOUR</u>			
35	Spray Paint (Front Bumper, Bonnet, Rear Bumper & Bootlid)	1	\$ 1,000.00	\$ 1,000.00
36	Remove and Refit Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00
37	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
38	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
39	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,210.00
Amount Before Excess				\$ 10,480.00
Add GST @ 7%				733.60
Total Amount Payable				\$ 11,213.60

Estimate prepared by: Oscar Pong
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.