

ASS. REC. BY:

REF:

C72/22011916/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10-10-30cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$2500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

31/12/22

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PKS3907J

Yr Regn:

01, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Camry G

c.c

2362

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

136342

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACV40

3142075

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Pir

R:

235/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

22/11/22

D.O.I.

29/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/1 1124 @ 1850 Car (Red, \$4029, 69%)

Date/Time, File Pass to?

1) 9/1/23

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

: Fines

: Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

1850

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 396A

Vehicle Details

Vehicle No.: SKS3907J
Vehicle to be Exported: No
Intended Deregistration Date: 23 Nov 2022
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.4G A
Primary Colour: Black
Manufacturing Year: 2007
Engine No.: 2AZC290879
Chassis No.: ACV403142075
Maximum Power Output: 123.0 kW (164 bhp)
Open Market Value: \$25,251.00
Original Registration Date: 12 Jan 2008
First Registration Date: 12 Jan 2008
Transfer Count: 1
Actual ARF Paid: \$27,777.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2022
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,925.00
COE Rebate Amount: \$543.00
Total Rebate Amount: \$543.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Nov 2022

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JEE NGIAP GHEE
 256 KIM KEAT AVE
 #07-148
 SINGAPORE 310256
 TEL: 98007122
 ATTN:

LICK
 10-1030
 29/11

Estimate No: MC1903139
 Date: 24 Nov 2022
 Policy No: MT/00738436/02
 Veh Reg No: SKS3907J
 Make/Model: TOYOTA CAMRY 2.4G A

Your Ref No: SKS3907J
 Claim Type: Third Party
 Accident Date: 22/11/2022
 TP Veh Reg No: GBD2691Y

SURVEYOR COPY

Not Authorized
 11/11/2022 @ 1850h
 Repairing After Paint
 3 days

Estimate Repair Cost to Vehicle No :SKS3907J

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 HEADLAMP ASSY LH	1 PC	2,800.75	X
2 FRONT BUMPER	1 PC	823.20	✓
3 FRONT BUMPER CLIPS	12 PC	57.60	✓
4 FRONT BUMPER TOP RUBBER	1 PC	137.80	X
5 FRONT BUMPER SIDE RETAINER LH	1 PC	91.60	✓
6 FOGLAMP LH	1 PC	236.90	X
7 FOG LAMP COVER RH	1 PC	75.80	X
8 FRONT FENDER LH	1 PC	812.75	✓
9 FRONT FENDER SIGNAL LAMP LH	1 PC	78.40	X
10 FRONT FENDER TOP GARNISH CLIPS	3 PC	11.10	X
11 FRONT FENDER COWLING RH	1 PC	175.77	✓
12 FRONT FENDER COWLING CLIPS	8 PC	25.60	✓
13 FRONT WHEEL HUB LH	1 PC	241.70	X
14 FRONT WHEEL BEARING LH	1 PC	189.70	X
		5,758.67	
		1,439.67	4,319.00
Special Nett			
15 TYRE LHF (235/45 R17) - CHK PRICE	1 PC	0.0000	X
16 SPORT RIM LHF - CHK PRICE	1 PC	0.0000	X
		0.00	0.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
19 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	80.00	X
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR FRONT DOOR LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	400/
22 TO SPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH	1 PC	700.00	400/
		1,560.00	1,560.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Less 25%
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JEE NGIAP GHEE
256 KIM KEAT AVE
#07-148
SINGAPORE 310256
TEL: 98007122

ATTN:

Your Ref No: SKS3907J
Claim Type: Third Party
Accident Date: 22/11/2022
TP Veh Reg No: GBD2691Y

Estimate No: MC1903139
Date: 24 Nov 2022
Policy No: MT/00738436/02
Veh Reg No: SKS3907J
Make/Model: TOYOTA CAMRY 2.4G A

Estimate Repair Cost to Vehicle No :SKS3907J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 5,879.00
		Add GST @ 7%	411.53
		Total Amount Payable	S\$ 6,290.53

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED NINETY AND CENTS FIFTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE