



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Ergo Insurance Pte Ltd
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 5
SINGAPORE 038985

Claim Details

Case Ref. No. : OD/112022/5814
Date : 25-11-2022
Accident Date : 24-11-2022

Vehicle Details

Make & Model : Toyota TOYOTA DYNA 150
MANUAL
Chassis No : JTFAT35YX0K205588
Registration No : GBE5732M

S/N	Description	Qty	Amount (\$)
1	FRONT WIPER PANEL / Bnc	1.00	\$160.00
2	FRONT WIPER PANEL LOWER PROTECTOR - C/A	1.00	\$180.00
3	FRONT RH WIPER ARM / Cut	1.00	\$80.00
4	FRONT LH WIPER ARM X NN	1.00	\$80.00
5	FRONT WIPER LINKAGE ?	1.00	\$210.00
6	FRONT WIPER MOTOR ?	1.00	\$500.00
7	WIPER NOZZIE ?	2.00	\$60.00
8	FRONT PANEL-OUTER / Bnc	1.00	\$720.00
9	FRONT GRILLE / C/A	1.00	\$280.00
10	FRONT GRILLE EMBLEM / spec.	1.00	\$40.00
11	FRONT GRILLE RUBBER / re	1.00	\$20.00
12	RH TOP CORNER PANEL	1.00	\$80.00
13	RH LOWER CORNER PANEL X NN	1.00	\$120.00
14	RH CORNER PANEL LOWER PROTECTOR	1.00	\$60.00
15	RH CORNER PANEL RETAINER X NN Cut	1.00	\$10.00
16	RH HEADLAMP / R's	1.00	\$400.00
17	LH HEADLAMP / RR	1.00	\$400.00
18	FRONT BUMPER / R's	1.00	\$240.00
19	FRONT WINDSCREEN GLASS RUBBER / MCC	1.00	\$180.00
20	AIRCON BLOWER UNIT ?	1.00	\$730.00
21	FRONT RH DOOR STEP GARNISH ?	1.00	\$170.00
22	FRONT LH DOOR STEP GARNISH X NN	1.00	\$170.00
23	FRONT CABIN BAR ?	1.00	\$410.00
24	POWER STEERING PUMP ?	1.00	\$920.00
25	FRONT BUMPER LH BRACKET MEMBER ?	1.00	\$90.00
26	CABIN MOUNTING BRACKET ?	1.00	\$260.00

Margin: 10%

\$6,570.00

\$657.00

\$7,227.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

27	FRONT NO. PLATE	1.00	\$40.00
28	ERP BRACKET	1.00	\$26.00
29	TO REMOVE AND REFIX FRONT WINDSCREEN	1.00	\$180.00 ¹²⁰
30	TO REPAIR DAMAGES	1.00	\$780.00 ⁶⁰⁰
31	TO SPRAY PAINTING	1.00	\$780.00 ✓

Subtotal w/o GST: \$9,033.00

5 Days.

P/P

before paint photos.

One Air

Excess: TBA

Not Authorized.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplemental survey may be surveyed and is subject to the Insurance Company

Acknowledged by: _____

Signature: _____

Date: _____

Issued by Iswan

This is a computer-generated document. No signature is required.