



Estimated Cost of Repair

Attention To : Ergo Insurance Pte Ltd
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER 5
SINGAPORE 038985

Claim Details

Case Ref. No. : OD/112022/5814
Date : 25-11-2022
Accident Date : 24-11-2022

Vehicle Details

Make & Model : Toyota TOYOTA DYNA 150
MANUAL
Chassis No : JTFAT35YX0K205588
Registration No : GBE5732M

S/N	Description	Qty	Amount (\$)
1	FRONT WIPER PANEL / <i>one</i>	1.00	\$160.00 ✓
2	FRONT WIPER PANEL LOWER PROTECTOR - <i>one</i>	1.00	\$180.00 ✓
3	FRONT RH WIPER ARM / <i>cut</i>	1.00	\$80.00 ✓
4	FRONT LH WIPER ARM X <i>nn</i>	1.00	\$80.00 X
5	FRONT WIPER LINKAGE ? <i>BT</i>	1.00	\$210.00 ✓
6	FRONT WIPER MOTOR ? X <i>nn</i>	1.00	\$500.00 X
7	WIPER NOZZIE ? <i>BR</i>	2.00	\$60.00 ✓
8	FRONT PANEL-OUTER / <i>one</i>	1.00	\$720.00 ✓
9	FRONT GRILLE / <i>one</i>	1.00	\$280.00 ✓
10	FRONT GRILLE EMBLEM / <i>one</i>	1.00	\$40.00 ✓
11	FRONT GRILLE RUBBER / <i>one</i>	1.00	\$20.00 ✓
12	RH TOP CORNER PANEL / <i>one</i>	1.00	\$80.00 ✓
13	RH LOWER CORNER PANEL X <i>nn</i>	1.00	\$120.00 X
14	RH CORNER PANEL LOWER PROTECTOR / <i>one</i>	1.00	\$60.00 ✓
15	RH CORNER PANEL RETAINER X <i>nn</i>	1.00	\$10.00 X
16	RH HEADLAMP / <i>R's</i>	1.00	\$400.00 ✓
17	LH HEADLAMP / <i>BR</i>	1.00	\$400.00 ✓
18	FRONT BUMPER / <i>R's</i>	1.00	\$240.00 ✓
19	FRONT WINDSCREEN GLASS RUBBER / <i>MCC</i>	1.00	\$180.00 ✓
20	AIRCON BLOWER UNIT ? <i>BR</i>	1.00	\$730.00 ✓
21	FRONT RH DOOR STEP GARNISH ? <i>BR</i>	1.00	\$170.00 ✓
22	FRONT LH DOOR STEP GARNISH X <i>nn</i>	1.00	\$170.00 X
23	FRONT CABIN BAR ? X <i>nn</i>	1.00	\$410.00 X
24	POWER STEERING PUMP ? X <i>nn</i>	1.00	\$920.00 X
25	FRONT BUMPER LH BRACKET MEMBER ? X <i>nn</i>	1.00	\$90.00 X
26	CABIN MOUNTING BRACKET ? X <i>nn</i>	1.00	\$260.00 X

4010
+10%
4411

Margin: 10%

\$6,570.00

\$657.00

\$7,227.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

27	FRONT NO.PLATE	1.00	\$40.00	✓
28	ERP BRACKET	1.00	\$26.00	✓
29	TO REMOVE AND REFIX FRONT WINDSCREEN	1.00	\$180.00	120
30	TO REPAIR DAMAGES	1.00	\$780.00	600
31	TO SPRAY PAINTING	1.00	\$780.00	✓

Subtotal w/o GST: \$9,033.00 1566

5977
supp 1 - 770
supp 2 - 700
7447

5 Days.

P/P

before paint photos.

One Air

Excess: TBA

Not Authorized.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental survey is to be surveyed and is subject to the insurance company

Acknowledged by:

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.