

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Senthilan Dillen Selvarajoo

Date: 19 Apr 2023

Preliminary Advice

Vehicle No	: GBE5732M	Accident Date	: 24/11/2022
Make	: TOYOTA DYNA 150 MANUAL	Policy No.	: DMCG22000886
Assignment Date	: 28/11/2022	Excess	: S\$750.00
Date of Inspection	: 29/11/2022	Est. Duration of Repair	: 8
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,503.00 (inclusive supp \$1,470.00)
Revised Amount	:S\$	7,447.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,447.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve supplementary.