



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4997D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WINDSCREEN GLASS	CHIPPED	750.00	750.00
1	FRONT WINDSCREEN GLASS MOULDING	NECESSARY	80.00	80.00
1	BONNET	TO REPAIR SEE LABOUR	1,100.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	380.00	-
1	FRONT HEADLAMP RH	CUT	1,200.00	1,200.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	730.00	-
1	FRONT BUMPER TOWING COVER	TO REPAIR SEE LABOUR	45.00	-
1	FRONT GRILLE	NOT NECESSARY	380.00	-
	LESS 10% DISCOUNT		-466.50	-203.00
			4,198.50	1,827.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	100.00	100.00
1	ERP BRACKET (SN)	NECESSARY	24.00	24.00
1	FRONT WINDSCREEN GLASS TINTED (SN)	NECESSARY	300.00	250.00
			424.00	374.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE AND REFIT FRONT WINDSCREEN GLASS.		100.00	100.00
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BONNET, FRONT FENDER RH, FRONT BUMPER AND FRONT BUMPER TOWING COVER.		800.00	400.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		40.00	30.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,000.00	600.00
			1,970.00	1,160.00
<b>GRAND TOTAL</b>			<b>6,592.50</b>	<b>3,361.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,361.00</b>

Report Ref No. CS/MSG22011925/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.