



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG22011925/Tqy3e2	
			Date: 29/12/2022	
			Code: MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SPALLING CONCRETE	<b>Veh. Inspected</b>	SLE 4997D
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	274211	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	LIM AI KIM	<b>Assign Date</b>	28/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	VOLKSWAGEN GOLF	<b>c.c</b>	1395
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	WVWZZZAUZGW329311	<b>Colour</b>	BLUE
	<b>Odometer</b>	70474 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	235/40 R18	BRIDGESTONE	6 mm
	<b>L/H Front Tyre</b>	235/40 R18	BRIDGESTONE	6 mm
	<b>R/H Rear Tyre</b>	235/40 R18	BRIDGESTONE	6 mm
	<b>L/H Rear Tyre</b>	235/40 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	30/04/2022	<b>Inspection Date</b>	05/12/2022
	<b>Survey held at</b>	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	