

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
 Singapore 737856
 Tel: Fax: Email:

INSURER :

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:	5126198075	Date of Loss:	30.04.2022
Vehicle Reg. No.:	SLE4997D	Driveable?	no
Driver Age:	13/09/1989	Third Party Vehicle No.:	NA
Any Injuries?	no	Contact No:	94246972
Insured/Claimant:	OMAR KHALIF S/O SHAIK HUSSAIN	Driver:	OMAR KHALIF S/O SHAIK HUSSAIN

PARTS MODEL

Make/Model:	Volkswagen, Golf - WVWZZZ1KZ9W571893	Vehicle Reg. Date:	
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss **DAMAGED BY PROPERTY**
 Remarks:
 Present Location: **Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG**

COST OF CLAIMS

	Amount
Parts	4,198.50
Miscellaneous Items	124.00
Labour	930.00
Paintwork Labour	1,040.00
Towing	0.00
Gross Total(S\$):	6,292.50
GST 7.00%(S\$):	440.48
Nett Amount(S\$):	6,732.98

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfhir 97495749/62563561
 WP' 05/12/22 @ 315pm
 tanfhir @ 1 hour 20 min
 3-4 days.

* Repair newer items & old items together.

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT WINDSCREEN GLASS	750.00	-10.00	675.00 <i>chipped</i>
2	1	FRONT WINDSCREEN GLASS MOULDING	80.00	-10.00	72.00 <i>new</i>
3	1	BONNET	1,100.00	-10.00	990.00 <i>Rx</i>
4	1	FRONT FENDER RH	380.00	-10.00	342.00 <i>Rx</i>
5	1	FRONT HEADLAMP RH	1,200.00	-10.00	1,080.00 <i>new</i>
6	1	FRONT BUMPER	730.00	-10.00	657.00 <i>Rx</i>
7	1	FRONT BUMPER TOWING COVER	45.00	-10.00	40.50 <i>Rx</i>
8	1	FRONT GRILLE	380.00	-10.00	342.00 <i>x</i>

Total Parts (S\$) 4,198.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT WINDSCREEN GLASS SEALANT	100.00	0.00	100.00 <i>new</i>
2	1	ERP BRACKET	24.00	0.00	24.00 <i>new</i>

Sub Total (S\$) 124.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Front Windscreen Glass.	100.00	0.00	100.00 ✓
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00 <i>400</i>

Gross Labour Cost (S\$) 930.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00	40.00 <i>30</i>
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,000.00	0.00	1,000.00 <i>600</i>

Gross Labour Cost (S\$) 1,040.00

< END OF ESTIMATES >