

ASS. REC: B: Taufik

REF: Q/ASM 2201/1980/TP3

ASSIGNMENT

LOE 2026 Rec

From: _____ Date: _____

Veh No: FBB1616H Yr Regn: 20061 Dec.

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / NS/TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: _____

Make: Yamaha T135 c.c. 135

at Workshop/s _____

Colour: Red A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 15269 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: 5YP 206317

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: _____

Modi: NP / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 90/80/147

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: 45K

Front: _____ Rear: _____

IDAC Accident Report: _____ Consistent?: Yes or No

R/Bal. 8 mm R/Bal. 5 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. _____ mm L/Bal. _____ mm

Est. Repairs: 3 days Res.: Yes or No

D.O.A. _____ D.O.L. 28/11/22

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at: Erz at we

CA / REV / REP. / 24 HRS _____

Des. of Damages: FR / Rear / O/S / NS / U/C / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit \$2400
	Taufikh finalised LS \$1100, 3 days. (Red 3562, 76%)

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 3

1) 29/05 Typist : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to? 2) _____

Add Fee: : Site Insp (\$ _____)) S + RS. \$ _____

: Interview (\$ _____)) Photos _____

: Tech. Invs (\$ _____)) Others _____

Report Format: SMART CLAIMS - TP

Lump Sum / I.E.H. / %

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatileemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 02-Nov-22

Estimate no.

1192

Plate No. FBB1616H

Model. SPARK 135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 350.00	✗ sh sw120	
2	FORK T-UNDER BRACKET	\$ 280.00	✗ n/a	
3	STEERING CONE	\$ 120.00	✗ n/a	
4	FRONT SPORT RIM	\$ 200.00	scr ✗ sw \$50	
5	FRONT TYRES SHAFT	\$ 100.00	✗ n/a	
6	ECU & CDI	\$ 350.00	✗ n/a	
7	FRONT NUMBER PLATE	\$ 30.00	SN 15 b7	
8	FRONT DAY LIGHT SET	\$ 250.00	✗ n/a 180	
9	HANDLE BAR	\$ 300.00	✗ n/a	
10	MIRROR SET	\$ 150.00	dis 80	
11	CLUTCH LEVER	\$ 80.00	at 40	
12	INNER COVER	\$ 280.00	✗ n/a 180	
13	INNER PANEL	\$ 150.00	✗ n/a	
14	COVERSET	\$ 450.00	✗ n/a 280	
15	FRONT FOOTREST BAR	\$ 250.00	✗ n/a	
16	FRONT FOOTREST RUBBER	\$ 50.00	at	
17	HANDLE BAR BRACKET	\$ 280.00	✗ n/a	
18	FRONT FAIRING INNER COVER	\$ 80.00	✗ n/a	
19	Front fender	\$ 60.00	cut	
20	BODY ALIGNMENT	\$ 300.00	7.20 ✗ n/a	
21	HEAD LIGHT	\$ 250.00	✗ n/a	
22	HORN STAY	\$ 280.00	✗ n/a	
23	LABOUR	\$ 500.00	300	

950
10/- 855
SN 185
300
1435
1/58 1100, 3 days

Tanferm 47495749
w/ 28/11/22 @ 340 p
4/5 Resurvey after repair
To check repair limit.
Tanferm @ Wharfedale
3-4 days

Less 10% \$ 518.00
\$ 5,180.00
Sub Total : \$ 4,662.00
GST 7% \$ 326.34
Total: \$ 4,988.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.