



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983
ATTN: HO WINNIE

Ref: CS/ASM22011930/Tqp3m4

Date: 30/05/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3162X	Veh. Inspected	FBB 1616H
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04FFC	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	28/11/2022

2. Vehicle Particulars & Condition

Make & Model	YAMAHA T135	c.c	135
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	5YP206317	Colour	RED
Odometer	15269 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80 R17	PIRELLI	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/11/2022	Inspection Date	28/11/2022
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**