



Case Details

Case Reference Number : TAX/11/22/2054
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1882J

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19920-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 27/11/2022 09:45 AM
 Vehicle Age(In Months) : 35

Documents / Photographs

[View Documents / Photographs](#)

Total Documents : 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Not Give	X <i>nn</i>
Standard	Main			COVER, RR BUMPER ASSY	1	525.40	525.40	25.00	394.05	Replace	1	394.05	Replace	<i>BR</i>
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	12.00	24.00	25.00	18.00	Replace	2	18.00	Replace	} <i>mc</i>
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	
Standard	Main			PAD, RR BUMPER, CTR	3	12.00	36.00	25.00	27.00	Replace	3	27.00	Replace	
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	12.30	24.60	25.00	18.45	Replace	2	18.45	Replace	
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	X <i>nn</i>
Standard	Main			RETAINER, RR BUMPER, RH	1	143.60	143.60	25.00	107.70	Replace	0	0	Check	?
Standard	Main			SEAL, RR BUMPER, RH	1	128.00	128.00	25.00	96.00	Replace	0	0	Not Give	X <i>nn</i>
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	<i>mc</i>
Standard	Main			GUARD, RR BUMPER, LOWER	1	405.00	405.00	25.00	303.75	Replace	1	303.75	Replace	<i>SR</i>
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	23.90	23.90	25.00	17.92	Replace	0	0	Not Give	X
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	42.20	42.20	25.00	31.65	Replace	0	0	Not Give	X <i>nn</i>

Total Spare Part Cost 4,176.68

Surveyor Total 810.15

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,176.68

Final Sur Total 810.15

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0	Not Give	X
Standard	Main			COVER, REAR FLOOR UNDER RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	X
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	X
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	367.30	367.30	10.00	330.57	Replace	0	0	Not Give	X
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	282.70	282.70	10.00	254.43	Replace	0	0	Not Give	X
Standard	Main			LAMP ASSY, REAR, RH	1	317.80	317.80	10.00	286.02	Replace	0	0	Not Give	X
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	X
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	10.00	70.20	Replace	0	0	Not Give	X
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	943.10	943.10	25.00	707.33	Replace	1	0	Repair	X Repair
Standard	Main			LINER, REAR FENDER, RH	1	151.10	151.10	25.00	113.32	Replace	0	0	Not Give	X
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Not Give	X
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X
Total Spare Part Cost									4,176.68	Surveyor Total 810.15				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,176.68	Final Sur Total 810.15				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	X
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	X
Total:			1,116.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	X X X } an
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	X NN
Total:			500.00	40.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,176.68	810.15
Total Labour Cost	676.00	200.00
Total Spray Painting	1,116.00	400.00
Other	500.00	40.00
Overall Total	6,468.68	1,450.15
Lump Sum Repair Option		☐
Lump Sum Total	0.00	1,450.15
Surveyor Approved Amount		1,450.15
No of Repair Days*	5	2

Remarks

Surveyor Name

Signature



PART BY PART / BEFORE PAINT PHOTO FOR CHECK ITEM
AND REPLACE ITEM PLEASE CALL SURVEYOR quociang
(LKK) & Email :quociang@lkkauto.com HP:82880282

GuoQiang

G

Save Clear

Survey Date

29/11/2022