


Section A - Accident Details

Registration Number	SHB1882J
Case Reference Number	TAX/11/22/2054
Registration Date	12/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHAN CHUAN WEE (ZENG QUANWEI)
Type of Accident	Side Swipe
Accident Date and Time	27/11/2022 5:45 PM
Accident Reported Date and Time	28/11/2022 10:36 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116966
Special Instruction to ARC, if any	REAR RIGHT PORTION
Prepared Date and Time	28/11/2022 1:21 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	


Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$4,284.38	\$917.85
Total Other Cost	\$500.00	\$40.00
TOTAL COST	\$6,576.38	\$1,557.85 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang (LKK) / III
ARC / Surveyor Sign Off Date	01/12/2022 1:56 PM	01/12/2022 1:44 PM
Signature		
Remarks	PART BY PART / BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quogiang (LKK) & Email :guogiang@lkkauto.com HP:82880282	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2301-0044	Invoice Number	
Quotation Date	06.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$40.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Not Given
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$143.60	0.00	\$0.00	Replace	Check
		52591-47080	SEAL, RR BUMPER , RH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace

X
√ be
√ } nec
√ } nec
√ } nec
√ } nec
X
X
X
√ br
√ nec

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/01/2023

User ID : PohSuan

		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$23.90	0.00	\$0.00	Replace	Not Given	X
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given	X
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given	X
		81580-47070	LAMP ASSY, REAR, RH	0.00	\$317.80	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
		65637-47060	LINER, REAR FENDER, RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total					\$5,187.30		\$810.15			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	25.00	\$107.70	Replace	Replace
Total					143.60		107.70		

✓ scr

917.85
 + 200.00
 + 440.00

 1,557.85