

MOTOR CLAIM RE-INSPECTION SURVEYOR ASSESSMENT PAPER REPORT

Claim No : IVS22/0480
Accident Date : 2/4/2022

Re-inspection Date : 8/4/2022
Report Date : 10/8/2022

Vehicle Description

Regn No : SMX2897K
Make & Model : HONDA SHUTTLE HYBRID 1.5A SENSING

Regn Date : 4/1/2021
Colour: BLUE

Re-inspection Findings

Re-inspection conducted at :


LOH & LEE MOTOR WORKSHOP

BLK 5 PIONEER ROAD NORTH #01-37

S (628458)

Affected Area :

Damaged along LHS portion (Slight damages)



Surveyor Re-inspection Report :

The vehicle was stationary in a appropriate position for us to conduct our inspection after the repair performed by the vehicle owner preferred workshop. During our visual inspection, we focus at the impact area that was consistent with the accident. We noticed that the vehicle have yet to repair state. However, few items are in serviceable condition. There is a price difference of S\$6,400.00 from the independent surveyor report that consist of parts that we viewed that was reusable. We have re-adjusted the repair amount that match our findings.

Summary	Workshop Repair Estimate \$	Independent Surveyor \$	Re-inspection Adjusted \$	Remarks
Parts:	3,660.96	3,660.96	30.00	
Labour:	5,200.00	4,050.00	920.00	
Special Nett:	950.00	920.00		
Others:				
Total :	9,810.96	8,630.96	950.00	
Lump Sum :		7,350.00	760.00	
Working days :	6.00	6.00	4.00	

* Units: Days - Hours - Panels (Labour + Mat) *Others: Aircon gas - Wheel align. - Electronic diagnostic - Tow - Glasses - Head-light align. Etc..

Re-inspection Findings Summary

Based on the documents and photographs provided/our physical re-inspection of the vehicle, we opine the repairs recommended were generally acceptable, except for the following items can be excluded on the basis as stated below :

[illegible][illegible][illegible]

Our Recommendation

We re-adjust the cost of recommended labour/parts from S\$9,810.96 to S\$760.00.

For your understanding of our re-adjustment on parts and labour, the detailed listings are in the sections 'Parts Supply', 'Special Nett Items' and 'Labour Charges' above.

According to our re-adjustment, the recommended lump sum repair costs is S\$760.00 , which includes spart parts cost of S\$30.00 and labour cost of S\$920.00 on lump sum basis. We would state in conclusion the claim for the repairs to be considered at S\$760.00 on a lump sum repair basis, with the repair period of 4 working days. In addition, attached are the photographs of the repaired vehicle taken during the reinspection.

Note: Using the paint thickness gauge, a reading of 0.2mm and above indicates repaired/used parts.

Prepared by : Sharin
For Liberty Insurance Pte Ltd

Signature (E): *Sharin*

20763/22:p

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Billing To: Tneoh Yunn Chung
c/o Loh & Lee Motor Workshop
Blk 5 #01-37
Pioneer Road North
Singapore 628458

Invoice no.: TP22040078

Date: 22 JUN 2022

Vehicle no: SMX2897K

Model : HONDA SHUTTLE HYBRID 1.5

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 08 APR 2022 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 600.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 600.00

Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.



AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP22040078

Date: 22 JUN 2022

Tneoh Yunn Chung
c/o Loh & Lee Motor Workshop
Blk 5 #01-37
Pioneer Road North
Singapore 628458

THIRD PARTY SURVEY ACCIDENT OCCURED ON 02 APR 2022

Workshop Name and Address	Loh & Lee Motor Workshop Blk 5 #01-37 Pioneer Road North Singapore 628458
---------------------------	--

As per your instruction dated	08 APR 2022	with regard to the above matter.
We have carried out a physical inspection on the said		SMX2897K
We enclosed herewith our report and findings as follows:		

1. VEHICLE PARTICULARS

Registration No : SMX2897K	Engine No : LEB7151359
Model : HONDA SHUTTLE HYBRID 1.5	Mileage : 047 731 km
Year / Capacity : Jan 2021 / 1496 cc	Colour : Metallic Blue
Chassis No : GP72117498	

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR O/S :	215/60/R16	Michelin	9.00 mm	Sport
FRONT N/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR N/S :	215/60/R16	Michelin	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMX2897K

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front bumper X Repair	bent	\$ 1,378.00	\$ 1,378.00
1 pc	Front bumper side retainer X Refit	bent	\$ 50.00	\$ 50.00
1 pc	Front bumper bracket X Refit	bent	\$ 96.60	\$ 96.60
10 pcs	Front bumper clips ✓ Necc	necessary	\$ 80.00	\$ S/N 30.00 80.00
1 pc	Headlamp assembly X grazed paint marked - polished	Distorted	\$ 2,151.60	\$ 2,151.60
1 pc	Front fender X Repair	dented	\$ 725.00	\$ 725.00
1 pc	Head lamp lower bracket X Refit	cracked	\$ 95.00	\$ 95.00
Parts Sub-Total			\$ 4,576.20	\$ 4,576.20
Discount 20.00%			\$ 915.24	\$ 915.24
			\$ 3,660.96	\$ 3,660.96

Vehicle Number : SMX2897K

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Front tyre (sport) X Reuse	damaged	\$ 350.00	\$ 320.00
1 pc	Front wheel rim (sport) X Reuse	damaged	\$ 600.00	\$ 600.00
Special Nett Sub-Total			\$ 950.00	\$ 920.00
Spare Parts Total			\$ 4,610.96	\$ 4,500.00

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 4,610.96	\$ 30.00 4,580.96
1	To check and reconnect snap wiring	\$ 180.00	\$ 20.00 150.00
2	To tuff coat affected areas	\$ 180.00	\$ X 150.00
3	To remove and refix interior upholstery	\$ 180.00	\$ 20.00 150.00
4	To respray affected areas	\$ 1,400.00	\$ 400.00 1,200.00
5	To check and adjust computer wheel alignment (before and after)	\$ 180.00	\$ 80.00 150.00
6	To renew damaged parts, straighten and repair front chassis member front RH door and aligned all parts	\$ 1,800.00	\$ 400.00 1,000.00
7	To apply paint coating protection (Receipt)	\$ 650.00	\$ 650.00
	Total	\$ 9,180.96	\$ 9,000.00
			950.00

The repairer has agreed to undertake the repair under Sum Basis. We have further adjusted the amount to a Sum Repair of :

\$ 7,350.00

760.00

4 repair days


Fong Kok Heng
Qualified Appraiser



羅 及 李 摩 哆
LOH & LEE MOTOR WORKSHOP

Business Registration No. 223943 / 00E

Block 5, Pioneer Road North, #01-37, Singapore 628458.

Tel: 268 0909 Pager: 9404 0172 Res: 566 1714

本號修理引擎・打嗎呷和噴漆等。

We Repair Motor Vehicle's Engine, Knocking Panel & Spraying.

TNEOH YUNN CHUNG

BLK 448 JURONG WEST ST 42

#12-234

SINGAPORE 640448

DATE: 22/06/22

DEAR SIRS

ACCIDENT DATE: 02/04/22

FINAL REPAIR BILL TO SMX 2897 K

LUMP SUM REPAIRS RECOMMENDED

BY THE SURVEYOR-----\$ 7,350.00

DOLLARS: SEVEN THOUSAND, THREE HUNDRED AND FIFTY ONLY

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	840D
Vehicle Details	
Vehicle No.:	SMX2897K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO SENSING
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	LEB7151359
Chassis No.:	GP72117498
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$24,145.00
Original Registration Date:	04 Jan 2021
First Registration Date:	04 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$10,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2031
PARF Rebate Amount:	\$8,102.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2031
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$45,510.00
COE Rebate Amount:	\$39,325.00
Total Rebate Amount:	\$47,427.00

The information contained herein is correct as at 08 Apr 2022

OK



Excellent Grip
Performance
Michelin 18"
Tyre



Prevent
Fading &
Stickiness
With...



KYB New SR
Special,
Better
Handling...



Android
Player w/
GPS
Navigation...

Mazda 3

Price Range

Depreciation

2017

Vehicle Type

Search



Advanced Search

Home » Used Cars » Tay Motor & Credit Pte Ltd » Honda Shuttle Hybrid 1.5A

Honda Shuttle Hybrid 1.5A

- Overview
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

Our Accreditations:



- Shortlist
- Compare
- Report Error
- More

Seller Information

Tay Motor & Credit Pte Ltd

9 vehicles for sale. 26 sold in past 3 mths

210 Turf Club Road Lot A3/A5
Car Mall @ The Grandstand
[Search cars nearby](#)

Jason Loh

81001755

Melvin Yeo

90074772

Ben Poh

90602520

Price	\$102,800		
Depreciation	\$11,220 /yr View models with similar depre	Reg Date	08-Jan-2021 (8yrs 8mths 30days COE left)
Mileage	9,800 km (7.9k /yr)	Manufactured	2018
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$46,191 as of today (change)	Fuel Type	Petrol-Electric
COE	\$45,012	OMV	\$22,883
Engine Cap	1,496 cc	ARF	\$9,037
Curb Weight	1,190 kg	Power	101.0 kW (135 bhp)
Type of Vehicle	Stationwagon	No. of Owners	1

Features
Reliable And Fuel Efficient 1.5L DOHC I-VTEC Engine. Hybrid. Producing 135 BHP, Airbags. ABS. 7 Speed Auto Transmission. Keyless Start/Stop. View specs of the [Honda Shuttle Hybrid \(2015\)](#)

Accessories
DVD Player With Bluetooth Interface, Reverse Camera/Sensors, Knockdown Rear Seats, Solar Film, ABS Braking System.

Description
Dark Blue. 1 Owner Only. Fuel Consumption 32.4km/l. Massive Saving From New Car. Buy And Drive. Low Mileage. Extremely Economical Yet Powerful. No Gimmicks. View To Believe. 100% Accident-Free. Trade In Welcome. Call Our Friendly Sales Rep To Arrange For A Viewing Today Before It's Gone!

Category
[e Car, Hybrid Cars](#)

Compare



