

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

TP III

Veron.

TO : MS JASMIYANTI (H/P : 97578703)

QUOTATION FOR SMK4078M HONDA JAZZ

24/11/2022

S/NO	QTY	PARTS TO BE REPLACE	
1	1	RH FRONT DOOR <i>Distorted</i>	\$560.00 ✓
2	2	RH FRONT DOOR HINGE @\$55.00 <i>Here</i>	\$110.00 X
3	1	RH FRONT DOOR CHECKER <i>Here</i>	\$55.00 X
4	1	RH FRONT DOOR INNER TRIM BOARD <i>Here</i>	\$387.00 X
5	1	RH FRONT DOOR INNER LOCK <i>Damaged</i>	\$260.00 ✓
6	1	RH FRONT DOOR OUTER LOCK WITH KEY <i>Dmd</i>	\$85.00 ✓
7	1	RH FRONT DOOR OUTER HANDLER <i>Same</i>	\$110.00 ✓
8	1	RH FRONT DOOR OUTER MOULDING <i>Del'd</i>	\$145.00 ✓
9	1	RH FRONT DOOR INNER RUBBER <i>Not new</i>	\$168.00 X
10	1	RH FRONT DOOR POWER WINDOW MOTOR <i>Damaged</i>	\$275.00 ✓
11	1	RH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>Dmd</i>	\$195.00 ✓
12	2	RH FRONT DOOR STICKER @\$48.00 <i>new</i>	\$96.00 ✓
13	1	RH FRONT DOOR FRONTAL GARNISH <i>Del'd</i>	\$65.00 ✓
14	1	RH FRONT DOOR GLASS <i>lt</i>	\$381.00 ✓
15	1	RH FRONT DOOR GLASS SOLAR FILM <i>new</i>	\$130.00 ✓
16	1	RH FRONT DOOR MIRROR <i>missing</i>	\$380.00 ✓
17	1	RH FRONT DOOR MIRROR COVER <i>missing</i>	\$75.00 ✓
18	1	RH REAR DOOR <i>Dented</i>	\$653.00 ✓
19	1	RH REAR DOOR FRONTAL RUBBER <i>lt</i>	\$102.00 ✓
20	1	RH FRONT FENDER <i>Repair</i>	\$223.00 +
21	1	RH FRONT HEADLAMP <i>lt</i>	\$445.00 ✓

3957

plus 15% : 4550.55

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No: 53231488C

page 2

QUOTATION FOR SMK4078M HONDA JAZZ

LABOUR

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE & TRANSFER ALL DOOR FITTING

1520

~~\$1,200.00~~ 600

~~\$1,400.00~~ 800

~~\$150.00~~ 120.

TOTAL : \$7,650.00

\$800.00

REMARK: 05 DAY REPAIR / PER DAYS CAR RENTAL \$160.00

TOTAL ALL : \$8,450.00

GST 7% \$591.50

GRAND TOTAL : \$9,041.50

total: 6070.55

4/s: 4.8K

0.5 Days

4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: