

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Chirn
Veron.

Page No. 1

Vehicle No. GBC860U

NISSAN CABSTAR

JN1SC2F24Z0801828

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	FRONT BUMPER <i>Deformed</i>			797.10		✓
2	FRONT BUMPER REINFORCEMENT <i>Bent</i>			545.20		✓
3	FRONT BUMPER FOG LAMP COVER @39.40 <i>xbr nec</i>			78.80		x.
4	FRONT GRILLE <i>crack d</i>			469.40		✓
5	FRONT GRILLE LOGO <i>new</i>			86.40		✓
6	FRONT PANEL <i>Dented.</i>			1412.10		✓
7	CABSTAR WORDING <i>new</i>			78.50		✓
8	FRONT CORNER PANEL @392.20 <i>xbr new</i>			784.40		x
9	FRONT WIPER PANEL <i>Dented</i>			553.60		✓
10	AIR CON BLOWER <i>crack d</i>			1143.80		✓
11	FRONT WINDSCREEN MOULDING <i>new</i>			185.90		✓
12	FRONT WING MIRROR COVER @95.90 <i>3 new</i>			191.80		x
13	FRONT WIPER ARM @85.40 <i>xbr nec</i>			170.80		x
				6497.80		
		less 10%		649.78	10%	
				5848.02		
	<u>SPECIAL NETT ITEMS</u>					
1	FRONT NUMBER PLATE <i>Bent</i>			30.00		✓
2	FRONT GRILLE CLIPS <i>new</i>			20.00		✓
3	FRONT PANEL SEALANT <i>new</i>			60.00		✓
4	FRONT WINDSCREEN SEALANT <i>Nec</i>			60.00		✓
				170		
		Total Parts		170.00		

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. GBC860U

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	PANEL BEATING	1400.00	800
2	SPRAY PAINTING	1200.00	600
3	WIRING	100.00	30.
4	TO APPLY TUFF COAT	150.00	40.
5	TO REMOVE FRONT WINDSCREEN	180.00	120.
6	TO REMOVE DASHBOARD	350.00	220.
7	TO REMOVE AIR CON SYSTEM & TO TOP UP AIR CON GAS	180.00	120.
	Labour Total :	3560.00	
	TOTAL (PARTS & LABOUR):	9578.02	

total: 6844.80
h/s: S.H.K.
07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: