



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011945/Tny3e2	
			Date: 23/12/2022	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 5589G	Veh. Inspected	SMU 971H	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS22/2057	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	28/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	GK82102712	Colour	WHITE	
Odometer	29823 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	WINDFORCE	6 mm	
L/H Front Tyre	185/60 R15	WINDFORCE	6 mm	
R/H Rear Tyre	185/60 R15	WINDFORCE	6 mm	
L/H Rear Tyre	185/60 R15	WINDFORCE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2022	Inspection Date	29/11/2022	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks				
A)REGISTRATION DATE: 24 JULY 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	