



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SKX7573K (CK)**
Your ref: **SJT562X**

Date: **25-Nov-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Email : MTCL@income.com.sg

NTUC Income Insurance company

1 Maritime Square
Harbourfront Centre
#10-01 Singapore 099253

Assessed Vehicle No : **SKX7573K**
Car Make and Model : **TOYOTA MARK X 2.5 A**
Date of Accident : **18-Nov-22**
Date of Assessment : **25-Nov-22**

We have carried out a physical assessment of SKX7573K at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : \$ 3,834.92
Est. Repair Days : 4



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.
No liability or responsibility whatsoever shall be held by **AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **SKX7573K**

Your Ref: **SJT562X**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT BUMPER <i>CL</i>		\$ 1,459.68
2	1	FRONT FENDER LH <i>X Repair</i>		\$ 425.50
3	1	HEAD LAMP LH <i>cut</i>		\$ 758.60
4	1	FRONT BUMPER SIDE RETAINER LH <i>X MR</i>		\$ 81.60
			SUB TOTAL	\$ 2,725.38
			LESS 25%	\$ 681.35
			TOTAL AMOUNT	\$ 2,044.04

Our Ref: **SKX7573K**

Your Ref: **SJT562X**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS <i>abc</i>		\$ 50.00
			SUB TOTAL	\$ 50.00
			TOTAL PARTS COST	\$ 2,094.04

Our Ref: **SKX7573K**

Your Ref: **SJT562X**

S/NO	DESCRIPTION	EST. BY WORKSHOP
1	LABOUR & PAINTWORK TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 600.00 <i>400</i>
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 80.00 <i>30</i>
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00 <i>400</i>
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 60.00 <i>X</i>
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 50.00 <i>X</i>
7	TO VACUUM, WAXING & CLEAN	\$ 50.00 <i>X</i>
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00 <i>X</i>
	TOTAL BEFORE GST	\$ 3,584.04
	GST 7%	\$ 250.88
	TOTAL (PARTS & LABOUR):	\$ 3,834.92

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 3,834.92** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

4 Days

Complete Repair

After repair photos

Gene Ong

7/12/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental survey is not to be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: